

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **20-11160**  
 Date of Acc: **08/03/20**  
 Time of Acc: **15:03** Hrs.  
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**  
 Officer: **OFFICER JAYSON HEIAR**  
 Badge #: **58**  
 Report Date: **08/03/2020**  
 Officer Notified: **15:03** Hrs.  
 Officer Arrived: **15:09** Hrs.  
 Scene Investigated: **YES**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **JACKSON - 49**  
 Acc Loc City: **MAQUOKETA - 4742**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00691760**  
 Y-Coordinate: **04657986**  
 Location Literal: **US 61**  
 Description:

**Unit 001**

Driver Name - Last: **PETERS**  
 First: **TIMOTHY**  
 Middle: **JAMES**  
 City: **DAVENPORT**  
 State: **IA**  
 Zip: **52802**  
 Suffix:  
 Gender: **Male**  
 Age: **29**  
 CDL: **NO**  
 License State: **IA**  
 License Class: **C**  
 License Endorsmnt:  
 License Restrictions: **S**  
 Speed Limit: **65**  
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**  
 Driver Condition: **01 - APPARENTLY NORMAL**  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **2**  
 Vehicle Year: **2020**  
 Vehicle Make: **CHEVROLET - CHEV**  
 Vehicle Model: **SILVERADO**  
 Vehicle Style: **TK**  
 Vehicle Color: **WHITE - WHI**  
 Vehicle Config: **11 - TRUCK/TRAILER**  
 Vehicle Defect: **01 - NONE**  
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**  
 Tow: **5 - NOT DISABLED - OFFICER ARRANGED**  
 Tow #: **20-107**  
 Initial Trvl Dir: **03 - SOUTH**  
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:  
 Dvr Distractions: **02 - NOT DISTRACTED**  
 Traffic Controls: **01 - NO CONTROLS PRESENT**  
 Point of Init Impact: **16 - CARGO LOSS**  
 Most Damaged Area: **16 - CARGO LOSS**  
 Undrrid/Ovrid: **1 - NONE**  
 Rpr/Rplc Cost: **\$0.00**  
 Ext of Damage: **1 - NONE**  
 First Event: **33 - VEHICLE IN TRAFFIC**  
 Second Event: **08 - CARGO/EQUIPMENT LOSS OR SHIFT**  
 Third Event:  
 Fourth Event:  
 Most Harmful Event: **08 - CARGO/EQUIPMENT LOSS OR SHIFT**  
 Abg Switch Stat:  
 Abg Deploy: **03 - NOT DEPLOYED**  
 Trapped: **1 - NOT TRAPPED/APPLICABLE**  
 Ejection: **2 - NOT EJECTED**  
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**  
 Occpnt Protect: **99 - UNKNOWN**  
 Source of Trans: **01 - NOT TRANSPORTED**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func: **01 - NO SPECIAL FUNCTION**  
 Emergency Status: **01 - NOT APPLICABLE**  
 Cont. Circum., Dvr: **57 - OVERLOADING/IMPROPER LOADING WITH PASSENGERS/CARGO**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1: **321.561**  
 Citation Charge 1: **DRIVING WHILE BARRED**  
 Cit Chrg Code 2: **321.460**  
 Citation Charge 2: **SPILLING LOADS ON HIGHWAY**  
 Citation Charge 3:  
 Citation Charge 4:

**Unit 002**

Driver Name - Last: <b>SEEBERGER</b>	Bus Use:	Transported to:
First: <b>SUSAN</b>		
Middle: <b>BERNADETTE</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>DUBUQUE</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52001</b>		
Suffix:	Point of Init Impact: <b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>10 - FRONT DRIVER SIDE</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Age: <b>66</b>	Undridd/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$2,500.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>3 - FUNCTIONAL DAMAGE</b>	
License Class: <b>C</b>	First Event: <b>33 - VEHICLE IN TRAFFIC</b>	
License Endorsmnt:		Carrier Name:
License Restrictions: <b>B</b>		Carrier Address:
Speed Limit: <b>65</b>		Carrier City:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Second Event: <b>38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O</b>	Carrier State:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>		Carrier Zip:
Alcohol Test Given: <b>NO</b>	Third Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Drug Test Given: <b>1 - NONE</b>	Fourth Event:	
Total Occupants: <b>1</b>		Number of Axles:
Vehicle Year: <b>2018</b>		HazMat Involvement:
Vehicle Make: <b>BUICK - BUIC</b>		HazMat Placard:
Vehicle Model: <b>LACROSSE ESSEN</b>	Most Harmful Event: <b>38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O</b>	Placard #:
Vehicle Style: <b>SD</b>		HazMat Released?:
Vehicle Color: <b>RED - RED</b>	Abg Switch Stat:	Converter Dolly:
Vehicle Config: <b>01 - PASSENGER CAR</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	GVWR:
Vehicle Defect: <b>01 - NONE</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	Cit Chrg Code 1:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>	Ejection: <b>2 - NOT EJECTED</b>	Citation Charge 1:
Tow: <b>1 - DRIVEN AWAY</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Cit Chrg Code 2:
	Occpnt Protect: <b>99 - UNKNOWN</b>	Citation Charge 2:
Tow #:		
Initial Trvl Dir: <b>03 - SOUTH</b>		Citation Charge 3:
Vision Obscured: <b>01 - NOT OBSCURED</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	
	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>33 - VEHICLE IN TRAFFIC</b>
Workers Present:	

**Narrative**

Unit 001 and Unit 002 were traveling southbound on Hwy 61 near the 157mm, when a tire from an unsecured load came off of the top of the trailer that was being towed by Unit 001, and struck the front and side of Unit 002 causing functional damage to Unit 002.

