

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **2020-14306**  
 Date of Acc: **09/27/20**  
 Time of Acc: **14:48** Hrs.  
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**  
 Officer: **OFFICER JASON THOMSON**  
 Badge #: **61**  
 Report Date: **09/27/2020**  
 Officer Notified: **14:51** Hrs.  
 Officer Arrived: **16:05** Hrs.  
 Scene Investigated: **YES**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **JACKSON - 49**  
 Acc Loc City: **MAQUOKETA - 4742**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00691753**  
 Y-Coordinate: **04658025**  
 Location Literal: **US 61**  
 Description:

**Unit 001**

Driver Name - Last: **THOMAS**  
 First: **NIA**  
 Middle: **L**  
 City: **DUBUQUE**  
 State: **IA**  
 Zip: **52001**  
 Suffix:  
 Gender: **Female**  
 Age: **23**  
 CDL: **NO**  
 License State: **IL**  
 License Class: **D**  
 License Endorsmnt:  
 License Restrictions:  
 Speed Limit: **65**  
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**  
 Driver Condition: **01 - APPARENTLY NORMAL**  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **4**  
 Vehicle Year: **2017**  
 Vehicle Make: **CHEVROLET - CHEV**  
 Vehicle Model: **MALIBU**  
 Vehicle Style: **LT**  
 Vehicle Color: **GRAY - GRY**  
 Vehicle Config: **01 - PASSENGER CAR**  
 Vehicle Defect: **01 - NONE**  
 Vehicle Action: **14 - NEGOTIATING A CURVE**  
 Tow: **5 - NOT DISABLED - OFFICER ARRANGED**  
 Tow #: **20-147**  
 Initial Trvl Dir: **01 - NORTH**  
 Vision Obscured: **98 - OTHER (EXPLAIN IN NARRATIVE)**

Bus Use:  
 Dvr Distractions: **02 - NOT DISTRACTED**  
 Traffic Controls: **01 - NO CONTROLS PRESENT**  
 Point of Init Impact: **01 - FRONT PASSENGER SIDE CORNER**  
 Most Damaged Area: **01 - FRONT PASSENGER SIDE CORNER**  
 Undrrid/Ovrid: **1 - NONE**  
 Rpr/Rplc Cost: **\$300.00**  
 Ext of Damage: **2 - MINOR DAMAGE**  
 First Event: **11 - LOSS OF TRACTION**  
 Second Event: **06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)**  
 Third Event: **01 - RAN OFF ROAD, RIGHT**  
 Fourth Event: **44 - DITCH**  
 Most Harmful Event: **44 - DITCH**  
 Abg Switch Stat:  
 Abg Deploy: **03 - NOT DEPLOYED**  
 Trapped: **1 - NOT TRAPPED/APPLICABLE**  
 Ejection: **2 - NOT EJECTED**  
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**  
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**  
 Source of Trans: **01 - NOT TRANSPORTED**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func: **01 - NO SPECIAL FUNCTION**  
 Emergency Status: **01 - NOT APPLICABLE**  
 Cont. Circum., Dvr: **06 - LOST CONTROL**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1:  
 Citation Charge 1:  
 Cit Chrg Code 2:  
 Citation Charge 2:  
 Citation Charge 3:  
 Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: **01 - ON ROADWAY**  
 Manner of Crash/Collision: **01 - NON-COLLISION (SINGLE VEHICLE)**  
 Light Conditions: **1 - DAYLIGHT**  
 Weather Conditions: **05 - RAIN**  
 Surface Conditions: **02 - WET**  
 Workzone Related: **NO**  
 Activity:  
 Location:  
 Type:  
 Workers Present:

**Roadway Characteristics**  
 Environment: **02 - WEATHER CONDITION**  
 Roadway: **02 - SURFACE CONDITION (E.G., WET, ICY)**  
 Type of Road Junc/Feat: **01 - NON-JUNCTION/NO SPECIAL FEATURE**  
 FRA No.:  
 Horizontal Alignment:  
 Vertical Alignment:  
 First Harmful Evt of Crash: **44 - DITCH**

**Narrative**

Unit one was traveling north bound on highway 61 while driving through the curve on the road unit one lost control (hydroplane) due to the road being wet and went into the east ditch. Minor damage to unit one. No injuries were reported. No damage to the fence or ditch.

Diagram

