

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	21-17551	Report to All Drivers:		At Intersection with:	
Date of Acc:	10/23/21	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	02:45 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	MAQUOKETA POLICE DEPARTMENT	County:	JACKSON - 49	Direction 1:	
Officer:	OFFICER RICHARD EWOLDT	Acc Loc City:	MAQUOKETA - 4742	Distance 2:	
Badge #:	64	Acc Dir From City:		Direction 2:	
Report Date:	10/23/2021	Closest City:		X-Coordinate:	00692065
Officer Notified:	02:51 Hrs.	Miles From City:		Y-Coordinate:	04659386
Officer Arrived:	02:55 Hrs.	Road,Street,HWay:		Location Literal Description:	WESTERN AVE
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	DORAN	Bus Use:		Transported to:	JACKSON COUNTY REGIONAL HOSPIT
First:	CREADANCE	Drvr Distractions:	99 - UNKNOWN	Transported by:	OFC EWOLDT
Middle:	JAYMZ	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	STERLING	Point of Init Impact:	11 - FRONT DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IL	Most Damaged Area:	11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	06 - LOST CONTROL, 16 - FAILED TO KEEP IN PROPER LANE
Zip:	61081-0000	Undrrid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$5,000.00	Carrier Name:	
Gender:	Male	Ext of Damage:	4 - DISABLING DAMAGE	Carrier Address:	
Age:	29	First Event:	03 - RAN OFF ROAD, LEFT	Carrier City:	
CDL:	NO	Second Event:	61 - LANDSCAPE/SHRUBBERY	Carrier State:	
License State:	IL	Third Event:	60 - TREE	Carrier Zip:	
License Class:	0	Fourth Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:		Most Harmful Event:	60 - TREE	Number of Axles:	
License Restrictions:		Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	25	Abg Deploy:	01 - NOT APPLICABLE	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	2 - EXTRICATED BY NON-MECHAN	Placard #:	
Driver Condition:	06 - UNDER THE INFLUENCE O	Ejection:	1 - NOT APPLICABLE	HazMat Released?:	
Alcohol Test Given:	REFUSED	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	GVWR:	
Total Occupants:	1	Source of Trans:	04 - LAW ENFORCEMENT	Cit Chrg Code 1:	321.288(1)
Vehicle Year:	2017	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Make:	DODGE - DODG			Cit Chrg Code 2:	321.20B
Vehicle Model:	GRAND CARAVAN			Citation Charge 2:	FAILURE TO PROVIDE PROOF OF FINANCIAL LIABILITY - ACC
Vehicle Style:	PV			Citation Charge 3:	
Vehicle Color:	BLACK - BLK			Citation Charge 4:	
Vehicle Config:	04 - PASSENGER VAN (SEATS <9)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	21-0190				
Initial Trvl Dir:	01 - NORTH				
Vision Obscured:	99 - UNKNOWN				

Property Damage 001

Object Damaged:	STONE LANDSCAPING AND TREE	Company Owner Name:	
Estimate of Damage:	\$2,000.00	City:	MAQUOKETA
Owner's Name - Last:	JACOBSEN	State:	IA
First:	LESLIE	Zip Code:	52060
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	06 - OUTSIDE TRAFFICWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	61 - LANDSCAPE/SHRUBBERY
Type:			
Workers Present:			

Narrative

On October 23rd, 2021 at approx 0245hrs Unit 1 was traveling North bound on Western Ave. Maquoketa, IA. Unit 1 failed to maintain control of the vehicle, left items lane,

and exited the roadway on the western/left side of road. Unit 1 entered onto the property of 408 Western Ave continued North Westerly and slightly uphill, before it struck and glanced off of a stone landscaping wall. Unit 1 struck the wall with the drivers side front bumper/fender, causing significant damage to the wall. Unit 1 continued essentially north and struck a tree with the drivers front bumper and fender causing disabling damage to Unit 1, and damage to the tree.

Diagram

