

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **20-15080**
 Date of Acc: **10/12/20**
 Time of Acc: **13:54** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER JAYSON HEIAR**
 Badge #: **58**
 Report Date: **10/12/2020**
 Officer Notified: **13:55** Hrs.
 Officer Arrived: **14:02** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00692081**
 Y-Coordinate: **04660043**
 Location Literal: **STATE 64/W PLATT ST**
 Description:

Unit 001

Driver Name - Last: **GREGORY**
 First: **SEAN**
 Middle: **JAMES**
 City: **DUBUQUE**
 State: **IA**
 Zip: **52002-0000**
 Suffix:
 Gender: **Male**
 Age: **18**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions: **BJ**
 Speed Limit: **30**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2005**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **TBZ**
 Vehicle Style: **SW**
 Vehicle Color: **GRAY - GRY**
 Vehicle Config: **11 - TRUCK/TRAILER**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **11 - STOPPED IN TRAFFIC**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **04 - WEST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **02 - TRAFFIC SIGNALS**
 Point of Init Impact: **06 - REAR MIDDLE**
 Most Damaged Area: **15 - NON-COLLISION/NO DAMAGE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$0.00**
 Ext of Damage: **1 - NONE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event: **38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O**
 Third Event:
 Fourth Event:
 Most Harmful Event: **38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **99 - UNKNOWN**
5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: LINDEN	Bus Use:	Transported to:
First: STACEY		
Middle: MARY	Drvr Distractions: 15 - INATTENTIVE/LOST IN THOUGHT	Transported by:
City: MAQUOKETA	Traffic Controls: 02 - TRAFFIC SIGNALS	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Zip: 52060-0000	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 07 - FOLLOWED TOO CLOSE
Suffix:	Undridd/Ovrid: 1 - NONE	
Gender: Female	Rpr/Rplc Cost: \$1,100.00	
Age: 57	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
CDL: NO	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License State: IA		Carrier Address:
License Class: C	Second Event: 38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O	Carrier City:
License Endorsmnt:	Third Event:	Carrier State:
License Restrictions:	Fourth Event:	Carrier Zip:
Speed Limit: 30	Most Harmful Event: 38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O	Cargo Body Type: 01 - NOT APPLICABLE
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Switch Stat:	Number of Axles:
Driver Condition: 01 - APPARENTLY NORMAL	Abg Deploy: 03 - NOT DEPLOYED	HazMat Involvement:
Alcohol Test Given: NO	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Placard:
Drug Test Given: 1 - NONE	Ejection: 2 - NOT EJECTED	Placard #:
Total Occupants: 1	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	HazMat Released?:
Vehicle Year: 2007	Occpnt Protect: 99 - UNKNOWN	Converter Dolly:
Vehicle Make: CHRYSLER - CHRY	Source of Trans: 01 - NOT TRANSPORTED	GVWR:
Vehicle Model: TOW	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Style: VN		Citation Charge 1:
Vehicle Color: SILVER - SIL		Cit Chrg Code 2:
Vehicle Config: 04 - PASSENGER VAN (SEATS <9)		Citation Charge 2:
Vehicle Defect: 01 - NONE		Citation Charge 3:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 4:
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

Unit 001 was stopped in traffic waiting for a signal change, when Unit 002 came from behind and struck the towed trailer of 001. The driver of 002 stated that she was not paying attention when she struck the 001.

Diagram

