

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 2020-11529	Report to All Drivers:	At Intersection with:
Date of Acc: 08/10/20	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 09:34 Hrs.	Private Property: NO	Distance 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Direction 1:
	Acc Loc City: MAQUOKETA - 4742	Distance 2:
Officer: OFFICER JASON THOMSON	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00693888
Badge #: 61	Miles From City:	Y-Coordinate: 04660117
Report Date: 08/10/2020	Road, Street, HWay:	Location Literal: STATE 64/E PLATT ST
Officer Notified: 09:34 Hrs.	Definable Location:	Description:
Officer Arrived: 09:38 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: PADAVICH	Bus Use:	Transported to:
First: KORY		
Middle: GREGORY	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 06 - REAR MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 06 - REAR MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 50	Undrriid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$300.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:	Second Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
Speed Limit: 30		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event: 33 - VEHICLE IN TRAFFIC	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event: 33 - VEHICLE IN TRAFFIC	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	HazMat Involvement:
Total Occupants: 2	Abg Switch Stat:	HazMat Placard:
Vehicle Year: 1994	Abg Deploy: 01 - NOT APPLICABLE	Placard #:
Vehicle Make: MAZDA - MAZD		HazMat Released?:
Vehicle Model: B23	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Style: PK	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Color: TURQUOISE (BLUE) - TRQ	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Vehicle Defect: 01 - NONE		Cit Chrg Code 2:
Vehicle Action: 10 - SLOWING/STOPPING (DECELERATING)		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #:		Citation Charge 4:
Initial Trvl Dir: 04 - WEST	Source of Trans: 01 - NOT TRANSPORTED	
Vision Obscured: 01 - NOT OBSCURED	Died at Scene: 01 - NOT APPLICABLE	

Unit 002

Driver Name - Last: TIES	Bus Use:	Transported to:
First: DARYL		
Middle: JOSEPH	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
Age: 55	Undridd/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:	Second Event: 33 - VEHICLE IN TRAFFIC	Carrier Address:
License Restrictions:	Third Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
Speed Limit: 30	Fourth Event: 33 - VEHICLE IN TRAFFIC	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Abg Switch Stat: 03 - NOT DEPLOYED	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Abg Deploy: 03 - NOT DEPLOYED	Number of Axles:
Drug Test Given: 1 - NONE	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Involvement:
Total Occupants: 1	Ejection: 2 - NOT EJECTED	HazMat Placard:
Vehicle Year: 2008	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Placard #:
Vehicle Make: BUICK - BUIC	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	HazMat Released?:
Vehicle Model: LUC	Source of Trans: 01 - NOT TRANSPORTED	Converter Dolly:
Vehicle Style: 4D	Died at Scene: 01 - NOT APPLICABLE	GVWR:
Vehicle Color: WHITE - WHI		Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR		Citation Charge 1:
Vehicle Defect: 01 - NONE		Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #:		Citation Charge 4:
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

Unit one was stopped on West Platt street waiting to turn left into Casey General store parking lot when unit two failed to notice unit one was stopped and rear ended unit one causing minor damage to both units. No injuries were reported.

Diagram

