

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>20-14609</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>10/03/20</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>10:35</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>MAQUOKETA POLICE DEPARTMENT</b>	County:	<b>JACKSON - 49</b>	Direction 1:	
Officer:	<b>SERGEANT KEENAN MEINECKE</b>	Acc Loc City:	<b>MAQUOKETA - 4742</b>	Distance 2:	
Badge #:	<b>56</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>10/03/2020</b>	Closest City:		X-Coordinate:	<b>00693140</b>
Officer Notified:	<b>10:40</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04659881</b>
Officer Arrived:	<b>10:45</b> Hrs.	Road,Street,HWay:		Location Literal Description:	<b>S MAIN ST</b>
Scene Investigated:	<b>YES</b>	Definable Location:			
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>WEIMERSKIRCH</b>	Bus Use:		Transported to:	
First:	<b>VIRGIL</b>	Drvr Distractions:	<b>02 - NOT DISTRACTED</b>	Transported by:	
Middle:	<b>FRANCIS</b>	Traffic Controls:	<b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:	<b>01 - NO SPECIAL FUNCTION</b>
City:	<b>LA MOTTE</b>	Point of Init Impact:	<b>06 - REAR MIDDLE</b>	Emergency Status:	<b>01 - NOT APPLICABLE</b>
State:	<b>IA</b>	Most Damaged Area:	<b>06 - REAR MIDDLE</b>	Cont. Circum., Drvr:	<b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>
Zip:	<b>52054-0000</b>	Undrrid/Ovrid:	<b>1 - NONE</b>	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	<b>\$200.00</b>	Carrier Address:	
Gender:	<b>Male</b>	Ext of Damage:	<b>2 - MINOR DAMAGE</b>	Carrier City:	
Age:	<b>78</b>	First Event:	<b>35 - PARKED MOTOR VEHICLE</b>	Carrier State:	
CDL:	<b>NO</b>	Second Event:		Carrier Zip:	
License State:	<b>IA</b>	Third Event:		Cargo Body Type:	<b>01 - NOT APPLICABLE</b>
License Class:	<b>C</b>	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	<b>35 - PARKED MOTOR VEHICLE</b>	HazMat Involvement:	
License Restrictions:	<b>BGJ</b>	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	<b>20</b>	Abg Deploy:	<b>03 - NOT DEPLOYED</b>	Placard #:	
Seating Position:	<b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped:	<b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:	
Driver Condition:	<b>01 - APPARENTLY NORMAL</b>	Ejection:	<b>1 - NOT APPLICABLE</b>	Converter Dolly:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:	
Drug Test Given:	<b>1 - NONE</b>	Occpnt Protect:	<b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:	
Total Occupants:	<b>2</b>	Source of Trans:	<b>01 - NOT TRANSPORTED</b>	Citation Charge 1:	
Vehicle Year:	<b>2009</b>	Died at Scene:	<b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:	
Vehicle Make:	<b>CHEVROLET - CHEV</b>			Citation Charge 2:	
Vehicle Model:	<b>SLV</b>			Citation Charge 3:	
Vehicle Style:	<b>PK</b>			Citation Charge 4:	
Vehicle Color:	<b>WHITE - WHI</b>				
Vehicle Config:	<b>02 - FOUR-TIRE TRUCK (PICK-UP)</b>				
Vehicle Defect:	<b>01 - NONE</b>				
Vehicle Action:	<b>09 - BACKING</b>				
Tow:	<b>1 - DRIVEN AWAY</b>				
Tow #:					
Initial Trvl Dir:	<b>03 - SOUTH</b>				
Vision Obscured:	<b>01 - NOT OBSCURED</b>				

**Unit 002**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City:		
State:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip:		
Suffix:	Point of Init Impact: <b>12 - FRONT MIDDLE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender:		
Age: <b>53</b>	Most Damaged Area: <b>12 - FRONT MIDDLE</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
CDL:		
License State:	Undrrid/Ovrid: <b>1 - NONE</b>	Carrier Name:
License Class:	Rpr/Rplc Cost: <b>\$200.00</b>	Carrier Address:
License Endorsmnt:	Ext of Damage: <b>2 - MINOR DAMAGE</b>	Carrier City:
License Restrictions:	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	Carrier State:
Speed Limit:		Carrier Zip:
Seating Position:		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
	Second Event:	
Driver Condition: <b>01 - APPARENTLY NORMAL</b>		
Alcohol Test Given:	Third Event:	
Drug Test Given:		
Total Occupants: <b>1</b>	Fourth Event:	
Vehicle Year: <b>2014</b>		Number of Axles:
Vehicle Make: <b>HYUNDAI - HYUN</b>		HazMat Involvement:
Vehicle Model: <b>SFE</b>		HazMat Placard:
Vehicle Style: <b>UT</b>	Most Harmful Event: <b>35 - PARKED MOTOR VEHICLE</b>	Placard #:
Vehicle Color: <b>SILVER - SIL</b>		HazMat Released?:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>		Converter Dolly:
	Abg Switch Stat:	GVWR:
Vehicle Defect: <b>01 - NONE</b>	Abg Deploy:	Cit Chrg Code 1:
		Citation Charge 1:
Vehicle Action: <b>12 - LEGALLY PARKED</b>	Trapped:	
	Ejection:	
Tow: <b>1 - DRIVEN AWAY</b>	Ejection Path:	Cit Chrg Code 2:
		Citation Charge 2:
Tow #:	Occpnt Protect:	
Initial Trvl Dir: <b>03 - SOUTH</b>		
Vision Obscured: <b>01 - NOT OBSCURED</b>		Citation Charge 3:
	Source of Trans:	
	Died at Scene:	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>07 - IN PARKING LANE/ZONE</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>03 - REAR END (FRONT TO REAR)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>35 - PARKED MOTOR VEHICLE</b>
Workers Present:	

**Narrative**

Unit 1 parked in a legal parking space located behind Unit 2. Before exiting the vehicle of Unit 1, Unit 2 started to back to exit parking space. Unit 1 used an audible horn to attempt to notify Unit 2. Unit 2 proceeded back and bumped Unit 1 causing minor damage to the front plate and skin of Unit 1. Unit 2 stated he did not hear the horn. Both units had minor damage.

Diagram

