

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **20-16116**  
 Date of Acc: **11/05/20**  
 Time of Acc: **12:25** Hrs.  
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**  
 Officer: **OFFICER RICHARD EWOLDT**  
 Badge #: **64**  
 Report Date: **11/05/2020**  
 Officer Notified: **12:25** Hrs.  
 Officer Arrived: **12:32** Hrs.  
 Scene Investigated: **YES**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **YES**  
 County: **JACKSON - 49**  
 Acc Loc City: **MAQUOKETA - 4742**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00693178**  
 Y-Coordinate: **04658684**  
 Location Literal: **S MAIN ST**  
 Description:

**Unit 001**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>01 - NOT APPLICABLE/NO DRIVER</b>	Transported by:
City:		
State:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip:		
Suffix:	Point of Init Impact: <b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender:	Most Damaged Area: <b>11 - FRONT DRIVER SIDE CORNER</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Age:	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL:	Rpr/Rplc Cost: <b>\$750.00</b>	
License State:	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class:	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:	Second Event:	Carrier City:
Speed Limit:	Third Event:	Carrier State:
Seating Position:	Fourth Event:	Carrier Zip:
		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Driver Condition:	Most Harmful Event: <b>35 - PARKED MOTOR VEHICLE</b>	Number of Axles:
Alcohol Test Given:	Abg Switch Stat:	HazMat Involvement:
Drug Test Given:	Abg Deploy:	HazMat Placard:
Total Occupants: <b>0</b>	Trapped:	Placard #:
Vehicle Year: <b>2012</b>	Ejection:	HazMat Released?:
Vehicle Make: <b>FORD - FORD</b>	Ejection Path:	Converter Dolly:
Vehicle Model: <b>XPL</b>	Occpnt Protect:	GVWR:
Vehicle Style: <b>SW</b>		Cit Chrg Code 1:
Vehicle Color: <b>BEIGE - BGE</b>	Source of Trans:	Citation Charge 1:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>	Died at Scene:	Citation Charge 2:
Vehicle Defect: <b>01 - NONE</b>		Citation Charge 3:
Vehicle Action: <b>12 - LEGALLY PARKED</b>		Citation Charge 4:
Tow: <b>1 - DRIVEN AWAY</b>		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

**Unit 002**

Driver Name - Last: <b>BOSTER</b>	Bus Use:	Transported to:
First: <b>PATRICIA</b>		
Middle: <b>DARLENE</b>	Drvr Distractions: <b>99 - UNKNOWN</b>	Transported by:
City: <b>LOST NATION</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52254</b>		
Suffix:	Point of Init Impact: <b>05 - REAR PASSENGER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>05 - REAR PASSENGER SIDE CORNER</b>	Cont. Circum., Drvr: <b>19 - STARTING OR BACKING IMPROPERLY</b>
Age: <b>82</b>	Undrrid/Ovrid: <b>9 - UNKNOWN</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost:	
License State: <b>IA</b>	Ext of Damage: <b>9 - UNKNOWN</b>	
License Class: <b>C</b>	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:	Second Event: <b>72 - HIT AND RUN</b>	Carrier City:
Speed Limit:		Carrier State:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Third Event:	Carrier Zip:
Driver Condition: <b>99 - UNKNOWN</b>	Fourth Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Alcohol Test Given: <b>NO</b>		Number of Axles:
Drug Test Given: <b>1 - NONE</b>	Most Harmful Event: <b>72 - HIT AND RUN</b>	HazMat Involvement:
Total Occupants: <b>1</b>		HazMat Placard:
Vehicle Year: <b>2009</b>	Abg Switch Stat:	Placard #:
Vehicle Make: <b>CHEVROLET - CHEV</b>	Abg Deploy: <b>99 - UNKNOWN</b>	HazMat Released?:
Vehicle Model: <b>IMPALA</b>		Converter Dolly:
Vehicle Style: <b>4D</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	GVWR:
Vehicle Color: <b>SILVER - SIL</b>	Ejection: <b>1 - NOT APPLICABLE</b>	Cit Chrg Code 1:
Vehicle Config: <b>01 - PASSENGER CAR</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Citation Charge 1:
Vehicle Defect: <b>99 - UNKNOWN</b>	Occpnt Protect: <b>99 - UNKNOWN</b>	Cit Chrg Code 2:
Vehicle Action: <b>09 - BACKING</b>		Citation Charge 2:
Tow: <b>1 - DRIVEN AWAY</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Citation Charge 3:
Tow #:	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 4:
Initial Trvl Dir: <b>01 - NORTH</b>		
Vision Obscured: <b>99 - UNKNOWN</b>		

**Accident Environment**

First Harmful Event Loc: <b>06 - OUTSIDE TRAFFICWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>03 - REAR END (FRONT TO REAR)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>35 - PARKED MOTOR VEHICLE</b>
Type:	
Workers Present:	

**Narrative**

On November 5th, 2020 Unit 1 was legally parked at City Limits Restaurant. Unit 2 Silver Chevrolet Impala partial IA plate 696Z..., reversed out of Handicap space striking Unit 1, with the rear Passenger side bumper of Unit 2 to the Front Drivers side bumper of Unit 1. Unit 2 drove back forward, before reversing again striking the Front Drivers bumper of Unit 1 a second time, with Unit 2's rear passenger bumper. Unit 1 sustained scratches and gouges, with silver paint transfer to the front drivers side bumper. Unit 2 then fled the scene.

Diagram

