

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>20-18576</b>	Report to All Drivers:	At Intersection with:
Date of Acc: <b>12/27/20</b>	Legal Intervention: <b>NO</b>	Div HWay Trvl Dir:
Time of Acc: <b>17:25</b> Hrs.	Private Property: <b>NO</b>	Distance 1:
Name of Agency: <b>MAQUOKETA POLICE DEPARTMENT</b>	County: <b>JACKSON - 49</b>	Direction 1:
Officer: <b>OFFICER NICHOLAS KONRARDY</b>	Acc Loc City: <b>MAQUOKETA - 4742</b>	Distance 2:
Badge #: <b>59</b>	Acc Dir From City:	Direction 2:
Report Date: <b>12/27/2020</b>	Closest City:	X-Coordinate: <b>00691752</b>
Officer Notified: <b>17:31</b> Hrs.	Miles From City:	Y-Coordinate: <b>04659901</b>
Officer Arrived: <b>17:31</b> Hrs.	Road, Street, HWay:	Location Literal: <b>US 61/SE RAMP</b>
Scene Investigated: <b>YES</b>	Definable Location:	Description:
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>ROBINSON</b>	Bus Use:	Transported to:
First: <b>BRITTANY</b>		
Middle: <b>ANN</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>MAQUOKETA</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52060-0000</b>		
Suffix:	Point of Init Impact: <b>05 - REAR PASSENGER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>05 - REAR PASSENGER SIDE CORNER</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
Age: <b>33</b>	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$500.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>3 - FUNCTIONAL DAMAGE</b>	
License Class: <b>C</b>	First Event: <b>11 - LOSS OF TRACTION</b>	
License Endorsmnt:		
License Restrictions: <b>B</b>	Second Event: <b>01 - RAN OFF ROAD, RIGHT</b>	Carrier Name:
Speed Limit: <b>65</b>		Carrier Address:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Third Event: <b>44 - DITCH</b>	Carrier City:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>		Carrier State:
Alcohol Test Given: <b>NO</b>	Fourth Event: <b>63 - FENCE</b>	Carrier Zip:
Drug Test Given: <b>1 - NONE</b>		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Total Occupants: <b>1</b>	Most Harmful Event: <b>63 - FENCE</b>	Number of Axles:
Vehicle Year: <b>2005</b>	Abg Switch Stat:	HazMat Involvement:
Vehicle Make: <b>CHRYSLER - CHRY</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	HazMat Placard:
Vehicle Model: <b>TOWN AND COUNTR</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	Placard #:
Vehicle Style: <b>VN</b>	Ejection: <b>2 - NOT EJECTED</b>	HazMat Released?:
Vehicle Color: <b>BLUE - BLU</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Converter Dolly:
Vehicle Config: <b>04 - PASSENGER VAN (SEATS &lt;9)</b>	Occpnt Protect: <b>01 - NOT APPLICABLE</b>	GVWR:
Vehicle Defect: <b>01 - NONE</b>		Cit Chrg Code 1: <b>321.20B</b>
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Citation Charge 1: <b>INSURANCE ACCIDENT</b>
Tow: <b>6 - ABANDONED/LEFT AT SCENE</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 2:
Tow #: <b>6</b>		Citation Charge 2:
Initial Trvl Dir: <b>01 - NORTH</b>		Citation Charge 3:
Vision Obscured: <b>01 - NOT OBSCURED</b>		Citation Charge 4:
	<b>5 - UNINJURED</b>	

**Property Damage 001**

Object Damaged: <b>FENCE</b>	Company Owner Name:
Estimate of Damage: <b>\$500.00</b>	City: <b>MAQUOKETA</b>
Owner's Name - Last: <b>DOT</b>	State: <b>IA</b>
First:	Zip Code: <b>52060</b>
Middle:	
Suffix:	

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>01 - NON-COLLISION (SINGLE VEHICLE)</b>	Environment: <b>02 - WEATHER CONDITION</b>
Light Conditions: <b>2 - DUSK</b>	Roadway: <b>02 - SURFACE CONDITION (E.G., WET, ICY)</b>
Weather Conditions: <b>07 - SNOW</b>	Type of Road Junc/Feat: <b>21 - OFF-RAMP, DIVERGE AREA</b>
Surface Conditions: <b>04 - SNOW</b>	
Workzone Related: <b>NO</b>	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: <b>44 - DITCH</b>
Workers Present:	

**Narrative**

Driver of unit one was traveling northbound on the Hwy 61 exit onto Platt St Maquoketa Iowa. The driver of unit one lost control of her mini van due to weather conditions and

went off the right side of the exit ramp. Unit one went down the hill towards the Fareway parking lot and struck a tree and hit the fence on the rear passenger side of the vehicle. the driver was not injured. recent purchase driver left old plate on vehicle.

**Diagram**

---

