

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **2020-7540**  
 Date of Acc: **06/01/20**  
 Time of Acc: **14:07** Hrs.  
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**  
 Officer: **OFFICER JASON THOMSON**  
 Badge #: **61**  
 Report Date: **06/01/2020**  
 Officer Notified: **14:07** Hrs.  
 Officer Arrived: **14:17** Hrs.  
 Scene Investigated: **YES**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **YES**  
 County: **JACKSON - 49**  
 Acc Loc City: **MAQUOKETA - 4742**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00693178**  
 Y-Coordinate: **04658676**  
 Location Literal: **906 S MAIN ST**  
 Description:

**Unit 001**

Driver Name - Last: <b>THOMAS</b>	Bus Use:	Transported to:
First: <b>CYNTHIA</b>		
Middle: <b>SUE</b>	Drvr Distractions: <b>99 - UNKNOWN</b>	Transported by:
City: <b>ANAMOSA</b>		
State: <b>IA</b>	Traffic Controls: <b>99 - UNKNOWN</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52205-0000</b>		
Suffix:	Point of Init Impact: <b>12 - FRONT MIDDLE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>12 - FRONT MIDDLE</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
Age: <b>65</b>	Undridd/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$2,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class: <b>C</b>	First Event: <b>99 - UNKNOWN</b>	
License Endorsmnt: <b>B</b>		Carrier Name:
Speed Limit: <b>0</b>	Second Event: <b>99 - UNKNOWN</b>	Carrier Address:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Third Event: <b>99 - UNKNOWN</b>	Carrier City:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Fourth Event: <b>99 - UNKNOWN</b>	Carrier State:
Alcohol Test Given: <b>NO</b>		Carrier Zip:
Drug Test Given: <b>1 - NONE</b>	Most Harmful Event: <b>99 - UNKNOWN</b>	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Total Occupants: <b>2</b>	Abg Switch Stat:	
Vehicle Year: <b>2016</b>	Abg Deploy: <b>01 - NOT APPLICABLE</b>	Number of Axles:
Vehicle Make: <b>FORD - FORD</b>		HazMat Involvement:
Vehicle Model: <b>ECP</b>	Trapped: <b>9 - UNKNOWN</b>	HazMat Placard:
Vehicle Style: <b>SW</b>	Ejection: <b>1 - NOT APPLICABLE</b>	Placard #:
Vehicle Color: <b>SILVER - SIL</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	HazMat Released?:
Vehicle Config: <b>01 - PASSENGER CAR</b>	Occpnt Protect: <b>01 - NOT APPLICABLE</b>	Converter Dolly:
Vehicle Defect: <b>99 - UNKNOWN</b>		GVWR:
Vehicle Action: <b>99 - UNKNOWN</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 1:
Tow: <b>1 - DRIVEN AWAY</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 1:
Tow #:		Cit Chrg Code 2:
Initial Trvl Dir: <b>99 - UNKNOWN</b>		Citation Charge 2:
Vision Obscured: <b>99 - UNKNOWN</b>		Citation Charge 3:
		Citation Charge 4:

**Unit 002**

Driver Name - Last: <b>BELL</b>	Bus Use:	Transported to:
First: <b>WILBUR</b>		
Middle: <b>CHARLEY</b>	Drvr Distractions: <b>99 - UNKNOWN</b>	Transported by:
City: <b>MAQUOKETA</b>		
State: <b>IA</b>	Traffic Controls: <b>99 - UNKNOWN</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52060-0000</b>		
Suffix:	Point of Init Impact: <b>06 - REAR MIDDLE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Male</b>		
Age: <b>64</b>	Most Damaged Area: <b>06 - REAR MIDDLE</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
CDL: <b>NO</b>	Undrrid/Ovrid: <b>1 - NONE</b>	
License State: <b>IA</b>	Rpr/Rplc Cost: <b>\$1,000.00</b>	
License Class: <b>C</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Endorsmnt: <b>L</b>	First Event: <b>99 - UNKNOWN</b>	Carrier Name:
License Restrictions: <b>B</b>		Carrier Address:
Speed Limit: <b>0</b>		Carrier City:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Second Event: <b>99 - UNKNOWN</b>	Carrier State:
		Carrier Zip:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Third Event: <b>99 - UNKNOWN</b>	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Alcohol Test Given: <b>NO</b>		
Drug Test Given: <b>1 - NONE</b>	Fourth Event: <b>99 - UNKNOWN</b>	Number of Axles:
Total Occupants: <b>2</b>		HazMat Involvement:
Vehicle Year: <b>2002</b>	Most Harmful Event: <b>99 - UNKNOWN</b>	HazMat Placard:
Vehicle Make: <b>DODGE - DODG</b>		Placard #:
Vehicle Model: <b>GRAND CARAVAN E</b>	Abg Switch Stat:	HazMat Released?:
Vehicle Style: <b>PC</b>	Abg Deploy: <b>01 - NOT APPLICABLE</b>	Converter Dolly:
Vehicle Color: <b>RED - RED</b>		GVWR:
Vehicle Config: <b>04 - PASSENGER VAN (SEATS &lt;9)</b>	Trapped: <b>9 - UNKNOWN</b>	Cit Chrg Code 1:
Vehicle Defect: <b>99 - UNKNOWN</b>	Ejection: <b>9 - UNKNOWN</b>	Citation Charge 1:
	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	
Vehicle Action: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Occpnt Protect: <b>99 - UNKNOWN</b>	Cit Chrg Code 2:
Tow: <b>1 - DRIVEN AWAY</b>		Citation Charge 2:
Tow #:		
Initial Trvl Dir: <b>99 - UNKNOWN</b>		
Vision Obscured: <b>99 - UNKNOWN</b>	<b>5 - UNINJURED</b>	Citation Charge 3:
	Source of Trans: <b>01 - NOT TRANSPORTED</b>	
	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>99 - UNKNOWN</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>99 - UNKNOWN</b>
Workers Present:	

**Narrative**

Unit two backed into unit one causing minor damage to both units. No injuries were reported. Incident happened on private property.

No Diagram / Private  
Property