

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **21-170**
 Date of Acc: **01/04/21**
 Time of Acc: **15:30** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **SERGEANT KEENAN MEINECKE**
 Badge #: **56**
 Report Date: **01/04/2021**
 Officer Notified: **15:31** Hrs.
 Officer Arrived: **15:36** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00693046**
 Y-Coordinate: **04659298**
 Location Literal: **S 2ND ST**
 Description:

Unit 001

Driver Name - Last: **FILLOON**
 First: **JOLENE**
 Middle: **MARY**
 City: **MAQUOKETA**
 State: **IA**
 Zip: **52060-0000**
 Suffix:
 Gender: **Female**
 Age: **60**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt: **L**
 License Restrictions:
 Speed Limit: **25**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **4**
 Vehicle Year: **2012**
 Vehicle Make: **FORD - FORD**
 Vehicle Model: **ECP**
 Vehicle Style: **SW**
 Vehicle Color: **WHITE - WHI**
 Vehicle Config: **03 - SPORT UTILITY VEHICLE**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **11 - STOPPED IN TRAFFIC**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **01 - NORTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **04 - STOP SIGNS**
 Point of Init Impact: **06 - REAR MIDDLE**
 Most Damaged Area: **06 - REAR MIDDLE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$1,500.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: HOFFMANN	Bus Use:	Transported to:
First: BRENDA		
Middle: KAY	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS
Age: 51	Undridd/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$1,500.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:		Carrier City:
Speed Limit: 25	Second Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 1		HazMat Placard:
Vehicle Year: 2003	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: SATU		HazMat Released?:
Vehicle Model: L300	Abg Switch Stat:	Converter Dolly:
Vehicle Style: PC	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Color: GRAY - GRY	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR	Ejection: 2 - NOT EJECTED	Citation Charge 1:
Vehicle Defect: 02 - BRAKE SYSTEM	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow: 1 - DRIVEN AWAY	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 3:
Tow #:	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 05 - SLUSH	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit 1 was stopped at the intersection waiting for traffic and was struck in the rear by Unit 2. Minor damage done to both units. No injuries.

Diagram

