

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **2021-0098**
 Date of Acc: **01/03/21**
 Time of Acc: **08:08** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER JASON THOMSON**
 Badge #: **61**
 Report Date: **01/03/2021**
 Officer Notified: **08:08** Hrs.
 Officer Arrived: **08:10** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00692211**
 Y-Coordinate: **04659483**
 Location Literal: **THOMAS AVE**
 Description:

Unit 001

Driver Name - Last: **MICHEL**
 First: **DEANNA**
 Middle: **LYNN**
 City: **MAQUOKETA**
 State: **IA**
 Zip: **52060-0000**
 Suffix:
 Gender: **Female**
 Age: **47**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions: **B**
 Speed Limit: **25**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **2**
 Vehicle Year: **2011**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **IMP**
 Vehicle Style: **4D**
 Vehicle Color: **SILVER - SIL**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **09 - BACKING**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **02 - EAST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **07 - REAR DRIVER SIDE CORNER**
 Most Damaged Area: **07 - REAR DRIVER SIDE CORNER**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$1,000.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **11 - LOSS OF TRACTION**
 Second Event: **35 - PARKED MOTOR VEHICLE**
 Third Event: **35 - PARKED MOTOR VEHICLE**
 Fourth Event: **35 - PARKED MOTOR VEHICLE**
 Most Harmful Event: **35 - PARKED MOTOR VEHICLE**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State:	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip:	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender:	Rpr/Rplc Cost: \$2,000.00	Carrier Name:
Age:	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
CDL:	First Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier City:
License State:	Second Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier State:
License Class:	Third Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Zip:
License Endorsmnt:	Fourth Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Number of Axles:
Speed Limit: 25	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
	Trapped:	Placard #:
Driver Condition:	Ejection:	HazMat Released?:
Alcohol Test Given:	Ejection Path:	Converter Dolly:
Drug Test Given:	Occpnt Protect:	GVWR:
Total Occupants: 0	Source of Trans:	Cit Chrg Code 1:
Vehicle Year: 2012	Died at Scene:	Citation Charge 1:
Vehicle Make: FORD - FORD		Cit Chrg Code 2:
Vehicle Model: FOC		Citation Charge 2:
Vehicle Style:		Cit Chrg Code 3:
Vehicle Color: GRAY - GRY		Citation Charge 3:
Vehicle Config: 01 - PASSENGER CAR		Citation Charge 4:
Vehicle Defect: 01 - NONE		
Vehicle Action: 12 - LEGALLY PARKED		
Tow: 1 - DRIVEN AWAY		
Tow #: 01 - NORTH		
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 02 - CLOUDY	Type of Road Junc/Feat: 05 - DRIVEWAY ACCESS (RELATED, NOT IN)
Surface Conditions: 04 - SNOW	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Type:	
Workers Present:	

Narrative

Unit one pulled into a private driveway off of Thomas Ave then proceeded backing out of the driveway. While backing out unit one lost traction due to the snow/icy road and couldn't stop and slid into unit two that was legally parked on the street. Unit two was unoccupied. There was minor damage to both units. No injuries were reported.

Diagram

