

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 2021-10017	Report to All Drivers:	At Intersection with:
Date of Acc: 07/02/21	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 09:18 Hrs.	Private Property: NO	Distance 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Direction 1:
	Acc Loc City: MAQUOKETA - 4742	Distance 2:
Officer: OFFICER JASON THOMSON	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00692226
Badge #: 61	Miles From City:	Y-Coordinate: 04660053
Report Date: 07/02/2021	Road, Street, HWay:	Location Literal: N JONES ST AND STATE 64/W
Officer Notified: 09:19 Hrs.	Definable Location:	Description: PLATT ST
Officer Arrived: 09:19 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: MICHELS	Bus Use:	Transported to:
First: DEANNA		
Middle: LYNN	Drvr Distractions: 97 - OTHER DISTRACTION INSIDE VEHICLE (EXPLAIN IN NARRATIVE)	Transported by:
City: MAQUOKETA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 05 - REAR PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip: 52060	Most Damaged Area: 05 - REAR PASSENGER SIDE CORNER	Cont. Circum., Drvr: 99 - UNKNOWN
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender: Female	Rpr/Rplc Cost: \$500.00	Carrier Name:
Age: 48	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
CDL: NO	First Event: 35 - PARKED MOTOR VEHICLE	Carrier City:
License State: IA	Second Event: 35 - PARKED MOTOR VEHICLE	Carrier State:
License Class: C	Third Event: 35 - PARKED MOTOR VEHICLE	Carrier Zip:
License Endorsmnt:	Fourth Event: 35 - PARKED MOTOR VEHICLE	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: B	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Number of Axles:
Speed Limit: 25	Abg Switch Stat:	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 03 - NOT DEPLOYED	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Total Occupants: 2	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Year: 2011	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: CHEVROLET - CHEV	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: IMPALA		Cit Chrg Code 2:
Vehicle Style: LT		Citation Charge 2:
Vehicle Color: SILVER - SIL		Citation Charge 3:
Vehicle Config: 01 - PASSENGER CAR		Citation Charge 4:
Vehicle Defect: 01 - NONE		
Vehicle Action: 09 - BACKING		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL:	Undridd/Ovrid: 1 - NONE	
License State:	Rpr/Rplc Cost: \$800.00	Carrier Name:
License Class:	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
License Endorsmnt:	First Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
License Restrictions:		Carrier State:
Speed Limit: 25	Second Event: 33 - VEHICLE IN TRAFFIC	Carrier Zip:
Seating Position:		Cargo Body Type: 01 - NOT APPLICABLE
	Third Event: 33 - VEHICLE IN TRAFFIC	
Driver Condition:		Number of Axles:
Alcohol Test Given:		HazMat Involvement:
Drug Test Given:		HazMat Placard:
Total Occupants: 0		Placard #:
Vehicle Year: 2010	Fourth Event: 33 - VEHICLE IN TRAFFIC	HazMat Released?:
Vehicle Make: TOYOTA - TOYT		Converter Dolly:
Vehicle Model: CAMRY		GVWR:
Vehicle Style: SE/LE/XL	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Cit Chrg Code 1:
Vehicle Color: SILVER - SIL		Citation Charge 1:
Vehicle Config: 01 - PASSENGER CAR	Abg Switch Stat:	
	Abg Deploy:	Cit Chrg Code 2:
Vehicle Defect: 01 - NONE		Citation Charge 2:
	Trapped:	
Vehicle Action: 12 - LEGALLY PARKED	Ejection:	
	Ejection Path:	Cit Chrg Code 3:
Tow: 1 - DRIVEN AWAY		Citation Charge 4:
	Occpnt Protect:	
Tow #: 03 - SOUTH		
Initial Trvl Dir:		
Vision Obscured:		
	Source of Trans:	
	Died at Scene:	

Accident Environment

First Harmful Event Loc: 06 - OUTSIDE TRAFFICWAY	Roadway Characteristics
Manner of Crash/Collision: 09 - REAR TO SIDE	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit one backed out of Dollar General Store parking lot onto Jones ave and struck unit two causing minor damage to both units. No injuries were reported. Unit two was legally parked and unoccupied.

Diagram

