

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>21-10781</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>07/12/21</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>08:30</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>MAQUOKETA POLICE DEPARTMENT</b>	County:	<b>JACKSON - 49</b>	Direction 1:	
Officer:	<b>OFFICER NICHOLAS KONRARDY</b>	Acc Loc City:	<b>MAQUOKETA - 4742</b>	Distance 2:	
Badge #:	<b>59</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>07/12/2021</b>	Closest City:		X-Coordinate:	<b>00693250</b>
Officer Notified:	<b>08:31</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04660292</b>
Officer Arrived:	<b>08:32</b> Hrs.	Road,Street,HWay:		Location Literal Description:	<b>E QUARRY ST</b>
Scene Investigated:	<b>NO</b>	Definable Location:			
		Milepost Number:			

**Unit 001**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>01 - NOT APPLICABLE/NO DRIVER</b>	Transported by:
City:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
State:	Point of Init Impact: <b>10 - FRONT DRIVER SIDE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Zip:	Most Damaged Area: <b>10 - FRONT DRIVER SIDE</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Suffix:	Undrriid/Ovrid: <b>1 - NONE</b>	
Gender:	Rpr/Rplc Cost: <b>\$1,500.00</b>	Carrier Name:
Age: <b>43</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	Carrier Address:
CDL:	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	Carrier City:
License State:	Second Event: <b>72 - HIT AND RUN</b>	Carrier State:
License Class:	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
License Restrictions:	Most Harmful Event: <b>72 - HIT AND RUN</b>	Number of Axles:
Speed Limit: <b>25</b>	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Trapped:	Placard #:
Alcohol Test Given:	Ejection:	HazMat Released?:
Drug Test Given:	Ejection Path:	Converter Dolly:
Total Occupants: <b>0</b>	Occpnt Protect:	GVWR:
Vehicle Year: <b>2012</b>	Source of Trans:	Cit Chrg Code 1:
Vehicle Make: <b>CHEVROLET - CHEV</b>	Died at Scene:	Citation Charge 1:
Vehicle Model: <b>TRV</b>		Cit Chrg Code 2:
Vehicle Style: <b>SW</b>		Citation Charge 2:
Vehicle Color: <b>GRAY - GRY</b>		Citation Charge 3:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>		Citation Charge 4:
Vehicle Defect: <b>01 - NONE</b>		
Vehicle Action: <b>12 - LEGALLY PARKED</b>		
Tow:		
Tow #:		
Initial Trvl Dir: <b>04 - WEST</b>		
Vision Obscured: <b>01 - NOT OBSCURED</b>		

**Unit 002**

Driver Name - Last: <b>OESTERN</b>	Bus Use: <b>05 - SHUTTLE</b>	Transported to:
First: <b>KATHRYN</b>		
Middle: <b>VIOLA</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>MAQUOKETA</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52060-0000</b>		
Suffix:	Point of Init Impact: <b>03 - MIDDLE PASSENGER SIDE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>03 - MIDDLE PASSENGER SIDE</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
Age: <b>69</b>	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL: <b>YES</b>	Rpr/Rplc Cost: <b>\$500.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class: <b>C</b>	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	
License Endorsmnt: <b>P - PASS</b>		Carrier Name:
License Restrictions: <b>BKLN</b>		Carrier Address:
Speed Limit: <b>25</b>		Carrier City:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Second Event: <b>72 - HIT AND RUN</b>	Carrier State:
		Carrier Zip:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Third Event:	Cargo Body Type: <b>20 - BUS</b>
Alcohol Test Given: <b>NO</b>	Fourth Event:	
Drug Test Given: <b>1 - NONE</b>		Number of Axles:
Total Occupants: <b>1</b>		HazMat Involvement:
Vehicle Year: <b>2018</b>		HazMat Placard:
Vehicle Make: <b>FORD - FORD</b>		Placard #:
Vehicle Model: <b>GLAVAL</b>	Most Harmful Event: <b>72 - HIT AND RUN</b>	HazMat Released?:
Vehicle Style: <b>BUS</b>		Converter Dolly:
Vehicle Color: <b>WHITE - WHI</b>	Abg Switch Stat: <b>01 - NOT APPLICABLE</b>	GVWR:
Vehicle Config: <b>24 - OTHER BUS (SEATS &gt;15)</b>	Abg Deploy: <b>01 - NOT APPLICABLE</b>	Cit Chrg Code 1:
		Citation Charge 1:
Vehicle Defect: <b>01 - NONE</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	
	Ejection: <b>1 - NOT APPLICABLE</b>	
Vehicle Action: <b>03 - TURNING RIGHT</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Cit Chrg Code 2:
		Citation Charge 2:
Tow: <b>1 - DRIVEN AWAY</b>	Occpnt Protect: <b>01 - NOT APPLICABLE</b>	
Tow #:		
Initial Trvl Dir: <b>04 - WEST</b>		
Vision Obscured: <b>01 - NOT OBSCURED</b>	<b>5 - UNINJURED</b>	Citation Charge 3:
	Source of Trans: <b>01 - NOT TRANSPORTED</b>	
	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>06 - SIDESWIPE, SAME DIRECTION</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>02 - CLOUDY</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>35 - PARKED MOTOR VEHICLE</b>
Workers Present:	

**Narrative**

ON THE ABOVE STATED DATE AND TIME UNIT 2 STRUCK PARKED UNIT ON WHILE WESTBOUND MAKING A RIGHT TURN FROM EAST QUARRY ST ONTO N OLIVE ST .

Diagram

