

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	2021-11330	Report to All Drivers:		At Intersection with:	
Date of Acc:	07/20/21	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	14:12 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	MAQUOKETA POLICE DEPARTMENT	County:	JACKSON - 49	Direction 1:	
Officer:	OFFICER SCOTT HANSEN	Acc Loc City:	MAQUOKETA - 4742	Distance 2:	
Badge #:	54	Acc Dir From City:		Direction 2:	
Report Date:	07/20/2021	Closest City:		X-Coordinate:	00693555
Officer Notified:	14:13 Hrs.	Miles From City:		Y-Coordinate:	04659597
Officer Arrived:	14:15 Hrs.	Road,Street,HWay:		Location Literal Description:	S MATTESON ST AND E LOCUST ST
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	BREWSTER CHRISTIAN	Bus Use:		Transported to:	JCRHC
First:	CHRISTIAN	Drvr Distractions:	99 - UNKNOWN	Transported by:	AMBULANCE
Middle:	DALE	Traffic Controls:	05 - YIELD SIGNS	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	MAQUOKETA	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Drvr:	08 - OPERATING VEHICLE IN A RECKLESS, ERRATIC, CARELESS, NEGLIGENT MANNER, 41 - FTYROW: FROM YIELD SIGN
Zip:	52060-0000	Undrrid/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$5,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:	4 - DISABLING DAMAGE	Carrier City:	
Age:	19	First Event:	33 - VEHICLE IN TRAFFIC	Carrier State:	
CDL:	NO	Second Event:	01 - RAN OFF ROAD, RIGHT	Carrier Zip:	
License State:	IA	Third Event:	57 - OTHER POST/POLE/SUPPORT (EXPLAIN IN NARRATIVE)	Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
License Restrictions:	B	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	25	Abg Deploy:	04 - DEPLOYED FRONT OF PERSON	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	99 - UNKNOWN	Cit Chrg Code 1:	321.322(2)
Total Occupants:	3	Source of Trans:	03 - EMS GROUND	Citation Charge 1:	FAIL TO OBEY YIELD SIGN
Vehicle Year:	2006	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Make:	AUDI - AUDI			Citation Charge 2:	
Vehicle Model:	A4 2.0T QUATTRO			Citation Charge 3:	
Vehicle Style:	4D			Citation Charge 4:	
Vehicle Color:	GRAY - GRY				
Vehicle Config:	01 - PASSENGER CAR				
Vehicle Defect:	99 - UNKNOWN				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	0				
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: SCHWEBKE	Bus Use:	Transported to:
First: DENNIS		
Middle: CRAIG	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: ANAMOSA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52205-0000		
Suffix:	Point of Init Impact: 08 - REAR DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 08 - REAR DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 65	Undridd/Ovrid: 1 - NONE	
CDL:	Rpr/Rplc Cost: \$5,000.00	
License State: IA	Ext of Damage: 4 - DISABLING DAMAGE	
License Class: A	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt: L		Carrier Name:
License Restrictions: BK	Second Event:	Carrier Address:
Speed Limit: 25	Third Event:	Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE		
Total Occupants: 1		Number of Axles:
Vehicle Year: 2006		HazMat Involvement:
Vehicle Make: CHEVROLET - CHEV		HazMat Placard:
Vehicle Model: SILVERADO	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Style: TRK		HazMat Released?:
Vehicle Color: WHITE - WHI	Abg Switch Stat:	Converter Dolly:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)	Abg Deploy: 99 - UNKNOWN	GVWR:
Vehicle Defect: 01 - NONE		Cit Chrg Code 1:
	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection: 2 - NOT EJECTED	
Tow: 3 - DISABLED - OFFICER ARRANGED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
		Citation Charge 2:
Tow #: 0	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	
Initial Trvl Dir: 03 - SOUTH		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Property Damage 001

Object Damaged: MATTESON LOCUST STREET SIGN	Company Owner Name: CITY OF MAQUOKETA
Estimate of Damage: \$350.00	City: MAQUOKETA
Owner's Name - Last:	State: IA
First:	Zip Code: 52060
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 05 - BROADSIDE (FRONT TO SIDE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
	Horizontal Alignment:
	Vertical Alignment:
Workzone Related: NO	
Activity:	
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Injured Person 001

Name - Last: BREWSTER	Airbag Deployment: 01 - NOT APPLICABLE
First: VICTORIA	
Middle:	
Suffix:	Airbag Switch Status:
City: MAQUOKETA	Trapped: 1 - NOT TRAPPED/APPLICABLE
State: IA	Injury Status: 4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)
Zip Code: 52060	Ejection: 2 - NOT EJECTED
Age: 16	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE
Sex: FEMALE	Alcohol Test Given:
Unit No.: 1	Drug Test Given:
Seating Position: 06 - 2ND ROW: RIGHT SIDE	Source of Transport: 05 - PARENT/SPOUSE/FRIEND
Occupant Protection: 02 - NONE USED	Died at Scene/Enroute: 01 - NOT APPLICABLE
	Transported to: JCRHC
	Transported by: AMBULANCE

Injured Person 002

Name - Last:	WATERMAN	Airbag Deployment:	04 - DEPLOYED FRONT OF PERSON
First:	DAVIS	Airbag Switch Status:	
Middle:	TAYLOR	Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	3 - SUSPECTED MINOR/NON-INCAPACITATING
City:	MAQUOKETA	Ejection:	1 - NOT APPLICABLE
State:	IA	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
Zip Code:	52060-2841	Alcohol Test Given:	
Age:	19	Drug Test Given:	
Sex:	MALE	Source of Transport:	03 - EMS GROUND
Unit No.:	1	Died at Scene/Enroute:	01 - NOT APPLICABLE
Seating Position:	03 - 1ST ROW: RIGHT SIDE	Transported to:	JCRHC
Occupant Protection:	02 - NONE USED	Transported by:	AMBULANCE

Narrative

On 7.20.21 at approximately 14:13 hours I was dispatched to 402 S. Matteson Street for a report of an accident. Vehicle 1 had driven west through a Yield sign at E. Locust and S. Matteson striking vehicle 2. Vehicle 2 was driving on S. Matteson going south through the intersection of E. Locust when vehicle 1 struck vehicle 2 in the rear left wheel. The collision caused vehicle 2 to spin 180 degrees stopped facing north and the rear left wheel was ripped off of vehicle 2. Vehicle 1 continued through the intersection leaving the roadway and striking a road sign before coming to a stop. Vehicle 1 had three occupants inside and both front air bags deployed in the accident. Both vehicle 1 and vehicle 2 were towed by Bridgeport Auto.

Diagram

