

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 2021-11449	Report to All Drivers:	At Intersection with:
Date of Acc: 07/22/21	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 08:44 Hrs.	Private Property: NO	Distance 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Direction 1:
Officer: ASST CHIEF BRENDAN ZEIMET	Acc Loc City: MAQUOKETA - 4742	Distance 2:
Badge #: 55	Acc Dir From City:	Direction 2:
Report Date: 07/22/2021	Closest City:	X-Coordinate: 00691508
Officer Notified: 08:48 Hrs.	Miles From City:	Y-Coordinate: 04658474
Officer Arrived: 08:51 Hrs.	Road, Street, HWay:	Location Literal: SWAGOSA/COUNTRY CLUB SR
Scene Investigated: YES	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: ROEDER	Bus Use:	Transported to:
First: MICHAEL		
Middle: GEORGE	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: ANDREW		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52030-0000		
Suffix:	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 61	Undrriid/Ovrid: 1 - NONE	
CDL: YES	Rpr/Rplc Cost: \$500.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: A	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt: X - HAZMAT & TANK		Carrier Address:
License Restrictions: BJ	Second Event:	Carrier City:
Speed Limit: 25		Carrier State:
Seating Position: 03 - 1ST ROW: RIGHT SIDE	Third Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 98 - OTHER (EXPLAIN IN NARRATIVE)
Alcohol Test Given: NO	Fourth Event:	Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 1	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	HazMat Placard:
Vehicle Year: 2010	Abg Switch Stat:	Placard #:
Vehicle Make: FREI	Abg Deploy: 01 - NOT APPLICABLE	HazMat Released?:
Vehicle Model: M2112	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Style: GARBAGE TK	Ejection: 1 - NOT APPLICABLE	GVWR:
Vehicle Color: RED - RED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 16 - OTHER HEAVY TRUCK (>10,000 LBS) (CANNOT CLASSI	Occpnt Protect: 99 - UNKNOWN	Citation Charge 1:
Vehicle Defect: 01 - NONE		Cit Chrg Code 2:
Vehicle Action: 02 - TURNING LEFT		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #: 01 - NORTH		Citation Charge 4:
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 01 - NOT TRANSPORTED	
	Died at Scene: 01 - NOT APPLICABLE	

Unit 002

Driver Name - Last: KOLL	Bus Use:	Transported to:
First: KENDRA		
Middle: SUE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 04 - REAR PASSENGER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female		
Age: 61	Most Damaged Area: 04 - REAR PASSENGER SIDE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
CDL: NO	Undridd/Ovrid: 1 - NONE	
License State: IA	Rpr/Rplc Cost: \$800.00	
License Class: C	Ext of Damage: 2 - MINOR DAMAGE	
License Endorsmnt:	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit: 25	Second Event:	Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE		
Total Occupants: 1		Number of Axles:
Vehicle Year: 2011		HazMat Involvement:
Vehicle Make: JEEP - JEEP		HazMat Placard:
Vehicle Model:		Placard #:
Vehicle Style: SW	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	HazMat Released?:
Vehicle Color: BLACK - BLK	Abg Switch Stat:	Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Defect: 01 - NONE		Cit Chrg Code 1:
	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
Vehicle Action: 02 - TURNING LEFT	Ejection: 2 - NOT EJECTED	
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow #:		Citation Charge 3:
Initial Trvl Dir: 01 - NORTH	Source of Trans: 01 - NOT TRANSPORTED	
Vision Obscured: 01 - NOT OBSCURED	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 13 - T-INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit 1 is a garbage truck that was making its rounds picking up trash. Unit 1 began to make a left turn. Unit 1 was turning on Country Club Drive as Unit 2 was attempting to pass Unit 1. Unit 2 took evasive action turning to the left in attempt to avoid the collision. Unit 1 and Unit 2 collided causing minor damage.

Diagram

