

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>21-11468</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>07/22/21</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>14:20</b> Hrs.	Private Property:	<b>YES</b>	Distance 1:	
Name of Agency:	<b>MAQUOKETA POLICE DEPARTMENT</b>	County:	<b>JACKSON - 49</b>	Direction 1:	
Officer:	<b>OFFICER NICHOLAS KONRARDY</b>	Acc Loc City:	<b>MAQUOKETA - 4742</b>	Distance 2:	
Badge #:	<b>59</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>07/22/2021</b>	Closest City:		X-Coordinate:	<b>00694303</b>
Officer Notified:	<b>14:20</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04660124</b>
Officer Arrived:	<b>14:21</b> Hrs.	Road,Street,HWay:		Location Literal Description:	<b>STATE 64/E PLATT ST</b>
Scene Investigated:	<b>YES</b>	Definable Location:			
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>FULTNER</b>	Bus Use:		Transported to:	
First:	<b>JOHN</b>	Drvr Distractions:	<b>02 - NOT DISTRACTED</b>	Transported by:	
Middle:	<b>ALLEN</b>	Traffic Controls:	<b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:	<b>01 - NO SPECIAL FUNCTION</b>
City:	<b>MAQUOKETA</b>	Point of Init Impact:	<b>99 - UNKNOWN</b>	Emergency Status:	<b>01 - NOT APPLICABLE</b>
State:	<b>IA</b>	Most Damaged Area:	<b>99 - UNKNOWN</b>	Cont. Circum., Drvr:	<b>99 - UNKNOWN</b>
Zip:	<b>52060</b>	Undrriid/Ovrid:	<b>8 - OTHER</b>		
Suffix:		Rpr/Rplc Cost:	<b>\$0.00</b>	Carrier Name:	
Gender:	<b>Male</b>	Ext of Damage:	<b>1 - NONE</b>	Carrier Address:	
Age:	<b>59</b>	First Event:	<b>99 - UNKNOWN</b>	Carrier City:	
CDL:	<b>NO</b>	Second Event:		Carrier State:	
License State:	<b>IA</b>	Third Event:		Carrier Zip:	
License Class:	<b>C</b>	Fourth Event:		Cargo Body Type:	<b>01 - NOT APPLICABLE</b>
License Endorsmnt:		Most Harmful Event:	<b>99 - UNKNOWN</b>	Number of Axles:	
License Restrictions:		Abg Switch Stat:		HazMat Involvement:	
Speed Limit:		Abg Deploy:	<b>01 - NOT APPLICABLE</b>	HazMat Placard:	
Seating Position:	<b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped:	<b>1 - NOT TRAPPED/APPLICABLE</b>	Placard #:	
Driver Condition:	<b>01 - APPARENTLY NORMAL</b>	Ejection:	<b>1 - NOT APPLICABLE</b>	HazMat Released?:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - NOT EJECTED/NOT APPLICABLE</b>	Converter Dolly:	
Drug Test Given:	<b>1 - NONE</b>	Occpnt Protect:	<b>01 - NOT APPLICABLE</b>	GVWR:	
Total Occupants:	<b>1</b>	Source of Trans:	<b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 1:	
Vehicle Year:	<b>1993</b>	Died at Scene:	<b>01 - NOT APPLICABLE</b>	Citation Charge 1:	
Vehicle Make:	<b>CHEVROLET - CHEV</b>			Cit Chrg Code 2:	
Vehicle Model:	<b>C35</b>			Citation Charge 2:	
Vehicle Style:	<b>PK</b>			Citation Charge 3:	
Vehicle Color:	<b>BLUE - BLU</b>			Citation Charge 4:	
Vehicle Config:	<b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>				
Vehicle Defect:	<b>01 - NONE</b>				
Vehicle Action:	<b>99 - UNKNOWN</b>				
Tow:	<b>1 - DRIVEN AWAY</b>				
Tow #:					
Initial Trvl Dir:	<b>99 - UNKNOWN</b>				
Vision Obscured:	<b>01 - NOT OBSCURED</b>				

**Unit 002**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City:		
State:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip:		
Suffix:	Point of Init Impact: <b>07 - REAR DRIVER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender:		
Age: <b>67</b>	Most Damaged Area: <b>07 - REAR DRIVER SIDE CORNER</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION, 99 - UNKNOWN</b>
CDL:		
License State:	Undrrid/Ovrid: <b>1 - NONE</b>	Carrier Name:
License Class:	Rpr/Rplc Cost: <b>\$1,400.00</b>	Carrier Address:
License Endorsmnt:	Ext of Damage: <b>2 - MINOR DAMAGE</b>	Carrier City:
License Restrictions:	First Event: <b>99 - UNKNOWN</b>	Carrier State:
Speed Limit:		Carrier Zip:
Seating Position:		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
	Second Event: <b>35 - PARKED MOTOR VEHICLE</b>	
Driver Condition: <b>01 - APPARENTLY NORMAL</b>		
Alcohol Test Given:	Third Event:	
Drug Test Given:		
Total Occupants: <b>3</b>	Fourth Event:	
Vehicle Year: <b>2006</b>		Number of Axles:
Vehicle Make: <b>CHEVROLET - CHEV</b>		HazMat Involvement:
Vehicle Model: <b>EQX</b>		HazMat Placard:
Vehicle Style: <b>SW</b>	Most Harmful Event: <b>35 - PARKED MOTOR VEHICLE</b>	Placard #:
Vehicle Color: <b>SILVER - SIL</b>		HazMat Released?:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>		Converter Dolly:
	Abg Switch Stat:	GVWR:
Vehicle Defect: <b>01 - NONE</b>	Abg Deploy:	Cit Chrg Code 1:
		Citation Charge 1:
Vehicle Action: <b>12 - LEGALLY PARKED</b>	Trapped:	
	Ejection:	
Tow:	Ejection Path:	Cit Chrg Code 2:
		Citation Charge 2:
Tow #:	Occpnt Protect:	
Initial Trvl Dir:		
Vision Obscured: <b>01 - NOT OBSCURED</b>		Citation Charge 3:
	Source of Trans:	
	Died at Scene:	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>99 - UNKNOWN</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>99 - UNKNOWN</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>04 - DRIVEWAY ACCESS (WITHIN)</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>99 - UNKNOWN</b>
Workers Present:	

**Narrative**

UNIT ONE STRUCK UNIT 2 WHILE ON HIS LAWN MOWER MAKING A TURN TO CONTINUE CUTTING GRASS. \*\*\*\* Explain the Vehicle Configuration for Unit 1