

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	21-12377	Report to All Drivers:		At Intersection with:	
Date of Acc:	08/06/21	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	01:03 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	MAQUOKETA POLICE DEPARTMENT	County:	JACKSON - 49	Direction 1:	
Officer:	OFFICER NICHOLAS KONRARDY	Acc Loc City:	MAQUOKETA - 4742	Distance 2:	
Badge #:	59	Acc Dir From City:		Direction 2:	
Report Date:	08/06/2021	Closest City:		X-Coordinate:	00694684
Officer Notified:	01:03 Hrs.	Miles From City:		Y-Coordinate:	04660106
Officer Arrived:	01:05 Hrs.	Road, Street, HWay:		Location Literal Description:	JACOBSEN DR AND STATE 64/E PLATT ST
Scene Investigated:	NO	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	RAAB	Bus Use:		Transported to:	
First:	BRANDON	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	DOUGLAS	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	CLINTON	Point of Init Impact:	11 - FRONT DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	58 - OPERATOR INEXPERIENCE
Zip:	52732	Undrriid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$500.00	Carrier Name:	
Gender:	Male	Ext of Damage:	2 - MINOR DAMAGE	Carrier Address:	
Age:	18	First Event:	01 - RAN OFF ROAD, RIGHT	Carrier City:	
CDL:	NO	Second Event:	44 - DITCH	Carrier State:	
License State:	IA	Third Event:		Carrier Zip:	
License Class:	C	Fourth Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:		Most Harmful Event:	44 - DITCH	Number of Axles:	
License Restrictions:		Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	25	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	1 - NOT APPLICABLE	HazMat Released?:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	GVWR:	
Total Occupants:	5	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 1:	
Vehicle Year:	2013	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	
Vehicle Make:	BUICK - BUIC			Cit Chrg Code 2:	
Vehicle Model:	VERANO			Citation Charge 2:	
Vehicle Style:	4D			Citation Charge 3:	
Vehicle Color:	WHITE - WHI			Citation Charge 4:	
Vehicle Config:	01 - PASSENGER CAR				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:	01 - NORTH				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	02 - SHOULDER	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	4 - DARK, ROADWAY LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

UNIT ONE WAS TRAVELING NORTHBOUND ON JACOBSEN ST. UNIT ONE CONTINUED STARIGHT AFTER STOPPING AT THE STOP SIGN AND DROVE OFF THE ROAD INTO A DITCH.

Diagram

