

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	21-16421	Report to All Drivers:		At Intersection with:	
Date of Acc:	10/06/21	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	00:23 Hrs.	Private Property:	YES	Distance 1:	
Name of Agency:	MAQUOKETA POLICE DEPARTMENT	County:	JACKSON - 49	Direction 1:	
Officer:	OFFICER MIKE OWEN	Acc Loc City:	MAQUOKETA - 4742	Distance 2:	
Badge #:	63	Acc Dir From City:		Direction 2:	
Report Date:	10/06/2021	Closest City:		X-Coordinate:	00693820
Officer Notified:	00:23 Hrs.	Miles From City:		Y-Coordinate:	04660483
Officer Arrived:	00:24 Hrs.	Road, Street, HWay:		Location Literal Description:	WALNUT ST
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	MANNING	Bus Use:		Transported to:	
First:	AMY	Drvr Distractions:	99 - UNKNOWN	Transported by:	
Middle:	MARIE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	LOST NATION	Point of Init Impact:	11 - FRONT DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	52254-0000	Undrrid/Ovrid:	9 - UNKNOWN		
Suffix:		Rpr/Rplc Cost:	\$3,500.00	Carrier Name:	
Gender:	Female	Ext of Damage:	4 - DISABLING DAMAGE	Carrier Address:	
Age:	43	First Event:	03 - RAN OFF ROAD, LEFT	Carrier City:	
CDL:	NO	Second Event:	65 - BUILDING	Carrier State:	
License State:	IA	Third Event:		Carrier Zip:	
License Class:	C	Fourth Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:		Most Harmful Event:	65 - BUILDING	Number of Axles:	
License Restrictions:	B	Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	25	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	06 - UNDER THE INFLUENCE O	Ejection:	2 - NOT EJECTED	HazMat Released?:	
Alcohol Test Given:	YES	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	GVWR:	
Total Occupants:	1	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 1:	321J.2 (2A)
Vehicle Year:	2010	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	OWI 1ST
Vehicle Make:	CHEVROLET - CHEV			Cit Chrg Code 2:	
Vehicle Model:	HHR			Citation Charge 2:	FAILURE TO MAINTAIN CONTROL
Vehicle Style:	SW			Citation Charge 3:	
Vehicle Color:	BLACK - BLK			Citation Charge 4:	
Vehicle Config:	01 - PASSENGER CAR				
Vehicle Defect:	99 - UNKNOWN				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:					
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	99 - UNKNOWN				

Property Damage 001

Object Damaged:	HOUSE	Company Owner Name:	
Estimate of Damage:	\$2,000.00	City:	MAQUOKETA
Owner's Name - Last:	SCHUELLER	State:	IA
First:	TOM	Zip Code:	52060
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	06 - OUTSIDE TRAFFICWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	4 - DARK, ROADWAY LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	65 - BUILDING
Type:			
Workers Present:			

Narrative

unit 1 was driving south on N. Walnut when vehicle crossed the center line jumped the curb and hit house located at 301 N. Walnut. Unit 1 then got back onto the road and

drove two blocks before stopping.

Diagram

