

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>2021-16599</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>10/08/21</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>19:00</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>MAQUOKETA POLICE DEPARTMENT</b>	County:	<b>JACKSON - 49</b>	Direction 1:	
Officer:	<b>SGT DARIN RISINGER</b>	Acc Loc City:	<b>MAQUOKETA - 4742</b>	Distance 2:	
Badge #:	<b>62</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>10/08/2021</b>	Closest City:		X-Coordinate:	<b>00692882</b>
Officer Notified:	<b>19:00</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04659575</b>
Officer Arrived:	<b>19:04</b> Hrs.	Road,Street,HWay:		Location Literal Description:	<b>W LOCUST ST</b>
Scene Investigated:	<b>YES</b>	Definable Location:			
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>EARLES</b>	Bus Use:		Transported to:	
First:	<b>DARIN</b>	Drvr Distractions:	<b>02 - NOT DISTRACTED</b>	Transported by:	
Middle:	<b>DAVID</b>	Traffic Controls:	<b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:	<b>01 - NO SPECIAL FUNCTION</b>
City:	<b>MAQUOKETA</b>	Point of Init Impact:	<b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status:	<b>01 - NOT APPLICABLE</b>
State:	<b>IA</b>	Most Damaged Area:	<b>11 - FRONT DRIVER SIDE CORNER</b>	Cont. Circum., Drvr:	<b>99 - UNKNOWN</b>
Zip:	<b>52060-0000</b>	Undrrid/Ovrid:	<b>1 - NONE</b>	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	<b>\$4,500.00</b>	Carrier Address:	
Gender:	<b>Male</b>	Ext of Damage:	<b>2 - MINOR DAMAGE</b>	Carrier City:	
Age:	<b>30</b>	First Event:	<b>35 - PARKED MOTOR VEHICLE</b>	Carrier State:	
CDL:	<b>NO</b>	Second Event:		Carrier Zip:	
License State:	<b>IA</b>	Third Event:		Cargo Body Type:	<b>01 - NOT APPLICABLE</b>
License Class:	<b>C</b>	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	<b>35 - PARKED MOTOR VEHICLE</b>	HazMat Involvement:	
License Restrictions:	<b>B</b>	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	<b>25</b>	Abg Deploy:	<b>03 - NOT DEPLOYED</b>	Placard #:	
Seating Position:	<b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped:	<b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:	
Driver Condition:	<b>01 - APPARENTLY NORMAL</b>	Ejection:	<b>1 - NOT APPLICABLE</b>	Converter Dolly:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:	
Drug Test Given:	<b>1 - NONE</b>	Occpnt Protect:	<b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:	
Total Occupants:	<b>1</b>	Source of Trans:	<b>01 - NOT TRANSPORTED</b>	Citation Charge 1:	
Vehicle Year:	<b>2014</b>	Died at Scene:	<b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:	
Vehicle Make:	<b>CHEVROLET - CHEV</b>			Citation Charge 2:	
Vehicle Model:	<b>CRZ</b>			Citation Charge 3:	
Vehicle Style:	<b>SD</b>			Citation Charge 4:	
Vehicle Color:	<b>RED - RED</b>				
Vehicle Config:	<b>01 - PASSENGER CAR</b>				
Vehicle Defect:	<b>01 - NONE</b>				
Vehicle Action:	<b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>				
Tow:	<b>1 - DRIVEN AWAY</b>				
Tow #:					
Initial Trvl Dir:	<b>04 - WEST</b>				
Vision Obscured:	<b>01 - NOT OBSCURED</b>				

**Unit 002**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>01 - NOT APPLICABLE/NO DRIVER</b>	Transported by:
City:		
State:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:
Zip:		
Suffix:	Point of Init Impact: <b>09 - MIDDLE DRIVER SIDE</b>	Emergency Status:
Gender:		
Age:	Most Damaged Area: <b>09 - MIDDLE DRIVER SIDE</b>	Cont. Circum., Drvr: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>
CDL:	Undrrid/Ovrid: <b>1 - NONE</b>	
License State:	Rpr/Rplc Cost: <b>\$2,000.00</b>	
License Class:	Ext of Damage: <b>3 - FUNCTIONAL DAMAGE</b>	
License Endorsmnt:	First Event:	Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit:	Second Event:	Carrier City:
Seating Position:		Carrier State:
	Third Event:	Carrier Zip:
Driver Condition:		Cargo Body Type:
Alcohol Test Given:	Fourth Event:	
Drug Test Given:		Number of Axles:
Total Occupants: <b>0</b>		HazMat Involvement:
Vehicle Year:		HazMat Placard:
Vehicle Make: <b>HOMEMADE - HMDE</b>		Placard #:
Vehicle Model: <b>TRAILER</b>	Most Harmful Event:	HazMat Released?:
Vehicle Style: <b>FLATBED</b>		Converter Dolly:
Vehicle Color: <b>BLACK - BLK</b>	Abg Switch Stat:	GVWR:
Vehicle Config: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Abg Deploy:	Cit Chrg Code 1:
Vehicle Defect:		Citation Charge 1:
	Trapped:	
Vehicle Action: <b>13 - ILLEGALLY PARKED/UNATTENDED</b>	Ejection:	
	Ejection Path:	Cit Chrg Code 2:
Tow:		Citation Charge 2:
	Occpnt Protect:	
Tow #:		
Initial Trvl Dir: <b>02 - EAST</b>		Citation Charge 3:
Vision Obscured:		
	Source of Trans:	
	Died at Scene:	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>06 - SIDESWIPE, SAME DIRECTION</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>4 - DARK, ROADWAY LIGHTED</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>35 - PARKED MOTOR VEHICLE</b>
Workers Present:	

**Narrative**

Vehicle number 1 was Westbound and struck a illegally parked flatbed trailer that was parked on the street.

Diagram

---

