

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **2021-17906**
 Date of Acc: **10/28/21**
 Time of Acc: **11:39** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER JASON THOMSON**
 Badge #: **61**
 Report Date: **10/28/2021**
 Officer Notified: **11:40** Hrs.
 Officer Arrived: **11:42** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00693132**
 Y-Coordinate: **04660144**
 Location Literal **N MAIN ST**
 Description:

Unit 001

Driver Name - Last: **FOWLER**
 First: **STEVEN**
 Middle: **ALLEN**
 City: **MAQUOKETA**
 State: **IA**
 Zip: **52060**
 Suffix:
 Gender: **Male**
 Age: **56**
 CDL: **YES**
 License State: **IA**
 License Class: **B**
 License Endorsmnt:
 License Restrictions: **P**
 Speed Limit: **20**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2012**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **SILVERADO**
 Vehicle Style: **K150**
 Vehicle Color: **SILVER - SIL**
 Vehicle Config: **02 - FOUR-TIRE TRUCK (PICK-UP)**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **01 - NORTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **01 - FRONT PASSENGER SIDE CORNER**
 Most Damaged Area: **01 - FRONT PASSENGER SIDE CORNER**
 Undrrid/Ovrid: **9 - UNKNOWN**
 Rpr/Rplc Cost: **\$3,000.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **34 - RE-ENTERING ROADWAY**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **34 - RE-ENTERING ROADWAY**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**
5 - UNINJURED

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: COLLINS	Bus Use:	Transported to:
First: STEPHEN		
Middle: DARNELL	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060		
Suffix:	Point of Init Impact: 10 - FRONT DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 10 - FRONT DRIVER SIDE	Cont. Circum., Drvr: 45 - FTYROW: FROM PARKED POSITION
Age: 21	Undrird/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:		Carrier City:
Speed Limit: 20	Second Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 1		HazMat Placard:
Vehicle Year: 2008	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: CHEVROLET - CHEV		HazMat Released?:
Vehicle Model: IMPALA	Abg Switch Stat:	Converter Dolly:
Vehicle Style: LTZ	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Color: RED - RED		Cit Chrg Code 1: 321.20B
Vehicle Config: 01 - PASSENGER CAR	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1: FAILURE TO PROVIDE PROOF OF FINANCIAL LIABILITY
Vehicle Defect: 03 - STEERING	Ejection: 2 - NOT EJECTED	Cit Chrg Code 2:
Vehicle Action: 17 - LEAVING A PARKED POSITION	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Citation Charge 2:
Tow: 1 - DRIVEN AWAY	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 3:
Tow #:		
Initial Trvl Dir: 01 - NORTH	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
Vision Obscured: 99 - UNKNOWN	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 02 - SHOULDER	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 03 - VISUAL OBSTRUCTION
Light Conditions: 1 - DAYLIGHT	Roadway: 99 - UNKNOWN
Weather Conditions: 05 - RAIN	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 02 - WET	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

Unit one was north bound on north Main Street when unit two was pulling out of a parking spot onto Main st and struck unit one causing minor damage to both units. No injuries were reported. Driver of unit two was charged with failure to have insurance.

