

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **21-21373**
 Date of Acc: **12/28/21**
 Time of Acc: **05:20** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER RICHARD EWOLDT**
 Badge #: **64**
 Report Date: **12/28/2021**
 Officer Notified: **05:20** Hrs.
 Officer Arrived: **05:26** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00692292**
 Y-Coordinate: **04657500**
 Location Literal: **US 61 S**
 Description:

Unit 001

Driver Name - Last: BUCK	Bus Use:	Transported to:
First: CAREY		
Middle: ANN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MONMOUTH		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52309-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female		
Age: 50	Most Damaged Area: 01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Drvr: 15 - OVER-CORRECTING/OVER-STEERING, 16 - FAILED TO KEEP IN PROPER LANE
CDL: NO	Undrriid/Ovrid: 1 - NONE	
License State: IA	Rpr/Rplc Cost: \$2,500.00	
License Class: C	Ext of Damage: 2 - MINOR DAMAGE	
License Endorsmnt:	First Event: 01 - RAN OFF ROAD, RIGHT	
License Restrictions:		
Speed Limit: 65	Second Event: 63 - FENCE	Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER		Carrier Address:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Carrier City:
Alcohol Test Given: NO		Carrier State:
Drug Test Given: 1 - NONE	Fourth Event:	Carrier Zip:
Total Occupants: 1		Cargo Body Type: 01 - NOT APPLICABLE
Vehicle Year: 2018	Most Harmful Event: 63 - FENCE	Number of Axles:
Vehicle Make: NISN	Abg Switch Stat:	HazMat Involvement:
Vehicle Model: KICKS	Abg Deploy: 01 - NOT APPLICABLE	HazMat Placard:
Vehicle Style: SUV	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Vehicle Color: BLACK - BLK	Ejection: 1 - NOT APPLICABLE	HazMat Released?:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Vehicle Defect: 01 - NONE	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Action: 02 - TURNING LEFT		Cit Chrg Code 1:
Tow: 4 - NOT DISABLED - PRIVATELY ARRANGED	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Tow #:	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
Initial Trvl Dir: 02 - EAST		Citation Charge 2:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 3:
		Citation Charge 4:

Property Damage 001

Object Damaged: BARBWIRE FENCE	Company Owner Name: IOWA DOT
Estimate of Damage: \$300.00	City:
Owner's Name - Last:	State:
First:	Zip Code:
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 06 - OUTSIDE TRAFFICWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 63 - FENCE
Workers Present:	

Narrative

On December 28th, 2021 Unit 1 was traveling South bound on Highway 61. Unit 1 while traversing a left hand curve, between the 158 mile marker and the 157 mile marker, Unit 1 left the road way to right catching the gravel shoulder. Unit 1 over corrected to the left back onto the roadway, before over correcting back to the right leaving the roadway. Unit 1 then traveled down hill through a barbwire fence before coming to stop in a field.

Diagram

