

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **2021-2341**
 Date of Acc: **02/27/21**
 Time of Acc: **11:15** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER JASON THOMSON**
 Badge #: **61**
 Report Date: **02/27/2021**
 Officer Notified: **11:15** Hrs.
 Officer Arrived: **11:20** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00693095**
 Y-Coordinate: **04660215**
 Location Literal: **JAMES ST**
 Description:

Unit 001

Driver Name - Last: **NABB**
 First: **BRIAN**
 Middle: **LEE**
 City: **MAQUOKETA**
 State: **IA**
 Zip: **52060-0000**
 Suffix:
 Gender: **Male**
 Age: **42**
 CDL: **YES**
 License State: **IA**
 License Class: **B**
 License Endorsmnt: **N - TANK**
 License Restrictions: **K**
 Speed Limit: **25**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **2**
 Vehicle Year: **2008**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **SLV**
 Vehicle Style: **PK**
 Vehicle Color: **BROWN - BRO**
 Vehicle Config: **02 - FOUR-TIRE TRUCK (PICK-UP)**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **02 - EAST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **02 - FRONT PASSENGER SIDE**
 Most Damaged Area: **02 - FRONT PASSENGER SIDE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$2,000.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**
5 - UNINJURED

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: LIPPER	Bus Use:	Transported to:
First: JENNIFER		
Middle: ROSE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 07 - REAR DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Most Damaged Area: 07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr: 45 - FTYROW: FROM PARKED POSITION
Age: 34	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: B	Second Event: 01 - RAN OFF ROAD, RIGHT	Carrier City:
Speed Limit: 25	Third Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 2		HazMat Placard:
Vehicle Year: 2012	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: CHEVROLET - CHEV	Abg Switch Stat:	HazMat Released?:
Vehicle Model: TRV	Abg Deploy: 03 - NOT DEPLOYED	Converter Dolly:
Vehicle Style: SW		GVWR:
Vehicle Color: BLACK - BLK	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR	Ejection: 2 - NOT EJECTED	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 09 - BACKING	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #:	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
Initial Trvl Dir: 01 - NORTH	Died at Scene: 01 - NOT APPLICABLE	
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 09 - REAR TO SIDE	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit one was eastbound on James Street when unit two was backing out of a parking spot. Driver of unit two did not see unit one and backed out of the parking spot striking unit one causing damage to both units. No injuries were reported.

Diagram

