

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **21-2904**
 Date of Acc: **03/10/21**
 Time of Acc: **15:53** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER REBECCA ARAGON**
 Badge #: **53**
 Report Date: **03/10/2021**
 Officer Notified: **15:53** Hrs.
 Officer Arrived: **15:58** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **YES**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00693382**
 Y-Coordinate: **04657960**
 Location Literal: **E CARLISLE ST**
 Description:

Unit 001

Driver Name - Last:
 First:
 Middle:
 City:
 State:
 Zip:
 Suffix:
 Gender:
 Age: **64**
 CDL:
 License State:
 License Class:
 License Endorsmnt:
 License Restrictions:
 Speed Limit:
 Seating Position:
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given:
 Drug Test Given:
 Total Occupants: **1**
 Vehicle Year: **2018**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **SILVERADO K1500**
 Vehicle Style: **PK**
 Vehicle Color: **GRAY - GRY**
 Vehicle Config: **02 - FOUR-TIRE TRUCK (PICK-UP)**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **12 - LEGALLY PARKED**
 Tow:
 Tow #:
 Initial Trvl Dir: **99 - UNKNOWN**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **01 - NOT APPLICABLE/NO DRIVER**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **09 - MIDDLE DRIVER SIDE**
 Most Damaged Area: **09 - MIDDLE DRIVER SIDE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$300.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **35 - PARKED MOTOR VEHICLE**
 Second Event: **33 - VEHICLE IN TRAFFIC**
 Third Event: **33 - VEHICLE IN TRAFFIC**
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy:
 Trapped:
 Ejection:
 Ejection Path:
 Occpnt Protect:
 Source of Trans:
 Died at Scene:

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

WALMART

ROW 6

