

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	21-6906	Report to All Drivers:		At Intersection with:	
Date of Acc:	05/15/21	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	13:43 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	MAQUOKETA POLICE DEPARTMENT	County:	JACKSON - 49	Direction 1:	
Officer:	OFFICER JAYSON HEIAR	Acc Loc City:	MAQUOKETA - 4742	Distance 2:	
Badge #:	58	Acc Dir From City:		Direction 2:	
Report Date:	05/15/2021	Closest City:		X-Coordinate:	00693156
Officer Notified:	13:43 Hrs.	Miles From City:		Y-Coordinate:	04659292
Officer Arrived:	13:43 Hrs.	Road,Street,HWay:		Location Literal Description:	S MAIN ST AND W SUMMIT ST AND E SUMMIT ST
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	LARSEN	Bus Use:		Transported to:	
First:	TODD	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	ROSS	Traffic Controls:	04 - STOP SIGNS	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	LONG GROVE	Point of Init Impact:	10 - FRONT DRIVER SIDE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	10 - FRONT DRIVER SIDE	Cont. Circum., Drvr:	88 - NO IMPROPER ACTION
Zip:	52756-0000	Undrriid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$10,000.00	Carrier Name:	
Gender:	Male	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier Address:	
Age:	57	First Event:	33 - VEHICLE IN TRAFFIC	Carrier City:	
CDL:	NO	Second Event:	38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O	Carrier State:	
License State:	IA	Third Event:		Carrier Zip:	
License Class:	C	Fourth Event:		Cargo Body Type:	14 - LARGE UTILITY TRAILER (2+AXLES)
License Endorsmnt:		Most Harmful Event:	38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O	Number of Axles:	
License Restrictions:	B	Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	25	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	HazMat Released?:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	99 - UNKNOWN	GVWR:	
Total Occupants:	1	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 1:	
Vehicle Year:	2002	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	
Vehicle Make:	CHEVROLET - CHEV			Cit Chrg Code 2:	
Vehicle Model:	SLV			Citation Charge 2:	
Vehicle Style:	PK			Citation Charge 3:	
Vehicle Color:	WHITE - WHI			Citation Charge 4:	
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	21-91				
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: JIMENEZ	Bus Use:	Transported to:
First: NATANAEL		
Middle:	Drvr Distractions: 15 - INATTENTIVE/LOST IN THOUGHT	Transported by:
City: MAQUOKETA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip: 52060-0000	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 42 - FTYROW: MAKING LEFT TURN, 58 - OPERATOR INEXPERIENCE
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender: Male	Rpr/Rplc Cost: \$15,000.00	Carrier Name:
Age: 18	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	Carrier Address:
CDL: NO	First Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
License State: IA	Second Event: 04 - CROSSED CENTERLINE (UNDIVIDED)	Carrier State:
License Class: C	Third Event: 38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: 2B	Most Harmful Event: 38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O	Number of Axles:
Speed Limit: 25	Abg Switch Stat: 04 - DEPLOYED FRONT OF PERSON	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 01 - NOT EJECTED/NOT APPLICABLE	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Released?:
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	Converter Dolly:
Drug Test Given: 1 - NONE	Ejection Path: 03 - SHOULDER AND LAP BELT USED	GVWR:
Total Occupants: 1	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1: 321.320
Vehicle Year: 2012	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1: FAIL TO YIELD UPON LEFT TURN
Vehicle Make: CHRYSLER - CHRY	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2: 321.193
Vehicle Model: TOW		Citation Charge 2: VIOLATION OF CONDITIONS OF RESTRICTED LICENSE
Vehicle Style: VN		Citation Charge 3:
Vehicle Color: BLUE - BLU		Citation Charge 4:
Vehicle Config: 04 - PASSENGER VAN (SEATS <9)		
Vehicle Defect: 01 - NONE		
Vehicle Action: 02 - TURNING LEFT		
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #: 21-91		
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 04 - ANGLE, ONCOMING LEFT TURN	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

UNIT 1 WAS TRAVELING SOUTHBOUND ON S. MAIN ST. AND SUMMIT ST. WHEN UNIT 2 MADE A LEFT TURN, FAILING TO YIELD ONCOMING TRAFFIC AND STRUCK UNIT 2 IN THE FRONT LEFT AND ALL THE WAY DOWN THE DRIVERS SIDE.

Diagram

