

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 21-7811	Report to All Drivers:	At Intersection with:
Date of Acc: 05/29/21	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 11:59 Hrs.	Private Property: NO	Distance 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Direction 1:
Officer: OFFICER MIKE OWEN	Acc Loc City: MAQUOKETA - 4742	Distance 2:
Badge #: 63	Acc Dir From City:	Direction 2:
Report Date: 05/29/2021	Closest City:	X-Coordinate: 00693156
Officer Notified: 11:59 Hrs.	Miles From City:	Y-Coordinate: 04659292
Officer Arrived: 12:00 Hrs.	Road, Street, HWay:	Location Literal: S MAIN ST AND W SUMMIT ST
Scene Investigated: YES	Definable Location:	Description: AND E SUMMIT ST
	Milepost Number:	

Unit 001

Driver Name - Last: SAID	Bus Use:	Transported to:
First: LINDA		
Middle: SUE	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Zip: 52060-0000	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 40 - FTYROW: FROM STOP SIGN
Suffix:	Undrrid/Ovrid: 9 - UNKNOWN	
Gender: Female	Rpr/Rplc Cost: \$5,000.00	Carrier Name:
Age: 72	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
CDL: NO	First Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
License State: IA		Carrier State:
License Class: C	Second Event:	Carrier Zip:
License Endorsmnt:	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Fourth Event:	Number of Axles:
Speed Limit: 25	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Switch Stat:	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Abg Deploy: 03 - NOT DEPLOYED	Placard #:
Alcohol Test Given: NO	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection: 2 - NOT EJECTED	Converter Dolly:
Total Occupants: 1	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	GVWR:
Vehicle Year: 2002	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:
Vehicle Make: HYUNDAI - HYUN		Citation Charge 1:
Vehicle Model: SFE	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 2:
Vehicle Style: SW	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 2:
Vehicle Color: SILVER - SIL		Citation Charge 3:
Vehicle Config: 03 - SPORT UTILITY VEHICLE		Citation Charge 4:
Vehicle Defect: 99 - UNKNOWN		
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		

Unit 002

Driver Name - Last: LIPPENS	Bus Use:	Transported to:
First: HEIDI		
Middle: JEAN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: CLINTON		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52732-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 53	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: B		Carrier City:
Speed Limit: 25	Second Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 1		HazMat Placard:
Vehicle Year: 2015	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: GENERAL MOTORS - GMC		HazMat Released?:
Vehicle Model: ACA	Abg Switch Stat:	Converter Dolly:
Vehicle Style: SW	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Color: GRAY - GRY	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Ejection: 2 - NOT EJECTED	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow: 1 - DRIVEN AWAY		
Tow #:	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 3:
Initial Trvl Dir: 02 - EAST	Died at Scene: 01 - NOT APPLICABLE	
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 05 - BROADSIDE (FRONT TO SIDE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit 1 was at the stop sign behind another vehicle a Jackson County Sheriff squad car. The squad car went through the intersection when unit 1 started through the intersection at the same time that unit 2 went through the intersection when unit 2 hit unit 1. When the squad went through the intersection they stated that their were cars at all 4 corners meaning that unit 1 behind them would not have had the right of way to proceed through the intersection.

