

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	2021-7997	Report to All Drivers:		At Intersection with:	
Date of Acc:	06/01/21	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	06:07 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	MAQUOKETA POLICE DEPARTMENT	County:	JACKSON - 49	Direction 1:	
Officer:	ASST CHIEF BRENDAN ZEIMET	Acc Loc City:	MAQUOKETA - 4742	Distance 2:	
Badge #:	55	Acc Dir From City:		Direction 2:	
Report Date:	06/01/2021	Closest City:		X-Coordinate:	00693993
Officer Notified:	06:07 Hrs.	Miles From City:		Y-Coordinate:	04660635
Officer Arrived:	06:10 Hrs.	Road,Street,HWay:		Location Literal Description:	1000-BLK E GROVE
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	FOX	Bus Use:		Transported to:	
First:	THEODORE	Drvr Distractions:	99 - UNKNOWN	Transported by:	
Middle:	HENRY	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	DE WITT	Point of Init Impact:	11 - FRONT DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	08 - OPERATING VEHICLE IN A RECKLESS, ERRATIC, CARELESS, NEGLIGENT MANNER
Zip:	52742-0000	Undrriid/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$1,300.00	Carrier Address:	
Gender:	Male	Ext of Damage:	2 - MINOR DAMAGE	Carrier City:	
Age:	19	First Event:	03 - RAN OFF ROAD, LEFT	Carrier State:	
CDL:	NO	Second Event:	59 - MAILBOX	Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	59 - MAILBOX	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	25	Abg Deploy:	03 - NOT DEPLOYED	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	06 - UNDER THE INFLUENCE O	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	YES	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	
Total Occupants:	1	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	
Vehicle Year:	2006	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Make:	FORD - FORD			Citation Charge 2:	
Vehicle Model:	EXPLORER EDDIE			Citation Charge 3:	
Vehicle Style:	4D			Citation Charge 4:	
Vehicle Color:	PURPLE - PLE				
Vehicle Config:	03 - SPORT UTILITY VEHICLE				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	5 - NOT DISABLED - OFFICER ARRANGED				
Tow #:					
Initial Trvl Dir:	02 - EAST				
Vision Obscured:	01 - NOT OBSCURED				

Property Damage 001

Object Damaged:	MAILBOX	Company Owner Name:	
Estimate of Damage:	\$0.00	City:	MAQUOKETA
Owner's Name - Last:	BELLINGS	State:	IA
First:	JACOB	Zip Code:	52060-2508
Middle:	RAY		
Suffix:			

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	3 - DAWN	Roadway:	01 - NONE APPARENT
Weather Conditions:	02 - CLOUDY, 03 - FOG, SMOKE, SMOG	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	59 - MAILBOX
Type:			
Workers Present:			

Narrative

Unit 1 was eastbound on East Grove Street when it drifted to the left traveling in the wrong lane of traffic and up onto a driveway/curb. Unit 1 struck a mailbox pole pushing

the pole to the side. Unit 1 drive was under the influence of alcohol.

Diagram

