

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>2021-8746</b>	Report to All Drivers:	At Intersection with:
Date of Acc: <b>06/12/21</b>	Legal Intervention: <b>NO</b>	Div HWay Trvl Dir:
Time of Acc: <b>13:34</b> Hrs.	Private Property: <b>NO</b>	Distance 1:
Name of Agency: <b>MAQUOKETA POLICE DEPARTMENT</b>	County: <b>JACKSON - 49</b>	Direction 1:
Officer: <b>SGT DARIN RISINGER</b>	Acc Loc City: <b>MAQUOKETA - 4742</b>	Distance 2:
Badge #: <b>62</b>	Acc Dir From City:	Direction 2:
Report Date: <b>06/12/2021</b>	Closest City:	X-Coordinate: <b>00693156</b>
Officer Notified: <b>13:34</b> Hrs.	Miles From City:	Y-Coordinate: <b>04659292</b>
Officer Arrived: <b>13:36</b> Hrs.	Road,Street,HWay:	Location Literal: <b>S MAIN ST AND W SUMMIT ST</b>
Scene Investigated: <b>YES</b>	Definable Location:	Description: <b>AND E SUMMIT ST</b>
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>JACOBS</b>	Bus Use:	Transported to:
First: <b>CHRISTINA</b>		
Middle: <b>IRENE</b>	Drvtr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>MAQUOKETA</b>		
State: <b>IA</b>	Traffic Controls: <b>04 - STOP SIGNS</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52060-0000</b>		
Suffix:	Point of Init Impact: <b>12 - FRONT MIDDLE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>12 - FRONT MIDDLE</b>	Cont. Circum., Drvr: <b>02 - RAN STOP SIGN</b>
Age: <b>58</b>	Undrriid/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$12,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>5 - SEVERE, VEHICLE TOTALED</b>	
License Class: <b>C</b>	First Event: <b>33 - VEHICLE IN TRAFFIC</b>	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: <b>B</b>	Second Event:	Carrier City:
Speed Limit: <b>25</b>		Carrier State:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Third Event:	Carrier Zip:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Alcohol Test Given: <b>NO</b>	Fourth Event:	
Drug Test Given: <b>1 - NONE</b>		Number of Axles:
Total Occupants: <b>3</b>	Most Harmful Event: <b>33 - VEHICLE IN TRAFFIC</b>	HazMat Involvement:
Vehicle Year: <b>2013</b>	Abg Switch Stat:	HazMat Placard:
Vehicle Make: <b>FORD - FORD</b>	Abg Deploy: <b>06 - DEPLOYED BOTH FRONT/SIDE</b>	Placard #:
Vehicle Model: <b>EDG</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:
Vehicle Style: <b>SW</b>	Ejection: <b>1 - NOT APPLICABLE</b>	Converter Dolly:
Vehicle Color: <b>BLACK - BLK</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:
Vehicle Defect: <b>01 - NONE</b>		Citation Charge 1:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 2:
Tow: <b>3 - DISABLED - OFFICER ARRANGED</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 2:
Tow #: <b>010115</b>		Citation Charge 3:
Initial Trvl Dir: <b>03 - SOUTH</b>		Citation Charge 4:
Vision Obscured: <b>01 - NOT OBSCURED</b>		

**Unit 002**

Driver Name - Last: <b>LANHART</b>	Bus Use:	Transported to:
First: <b>JORDAN</b>		
Middle: <b>DANIEL</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>MAQUOKETA</b>		
State: <b>IA</b>	Traffic Controls: <b>04 - STOP SIGNS</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>52060-0000</b>		
Suffix:	Point of Init Impact: <b>10 - FRONT DRIVER SIDE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Male</b>	Most Damaged Area: <b>10 - FRONT DRIVER SIDE</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Age: <b>25</b>	Undridd/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$15,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>5 - SEVERE, VEHICLE TOTALED</b>	
License Class: <b>C</b>	First Event: <b>33 - VEHICLE IN TRAFFIC</b>	
License Endorsmnt:		Carrier Name:
License Restrictions: <b>B</b>		Carrier Address:
Speed Limit: <b>25</b>	Second Event:	Carrier City:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Third Event:	Carrier State:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Fourth Event:	Carrier Zip:
Alcohol Test Given: <b>NO</b>		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Drug Test Given: <b>1 - NONE</b>		
Total Occupants: <b>2</b>		Number of Axles:
Vehicle Year: <b>2005</b>		HazMat Involvement:
Vehicle Make: <b>CHEVROLET - CHEV</b>		HazMat Placard:
Vehicle Model: <b>SLV</b>	Most Harmful Event: <b>33 - VEHICLE IN TRAFFIC</b>	Placard #:
Vehicle Style: <b>PK</b>		HazMat Released?:
Vehicle Color: <b>RED - RED</b>	Abg Switch Stat:	Converter Dolly:
Vehicle Config: <b>02 - FOUR-TIRE TRUCK (PICK-UP)</b>	Abg Deploy: <b>01 - NOT APPLICABLE</b>	GVWR:
Vehicle Defect: <b>01 - NONE</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	Cit Chrg Code 1:
	Ejection: <b>1 - NOT APPLICABLE</b>	Citation Charge 1:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	
Tow: <b>3 - DISABLED - OFFICER ARRANGED</b>	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 2:
		Citation Charge 2:
Tow #: <b>010115</b>		
Initial Trvl Dir: <b>02 - EAST</b>		Citation Charge 3:
Vision Obscured: <b>01 - NOT OBSCURED</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	
	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>05 - BROADSIDE (FRONT TO SIDE)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>12 - FOUR-WAY INTERSECTION</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>33 - VEHICLE IN TRAFFIC</b>
Workers Present:	

**Narrative**

Vehicle 1 ran the stop sign at the intersection and struck vehicle 2

Diagram

