

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement	Scene Investigated: YES	At Intersection with:
Case Number: 2022-1163	Report to All Drivers:	Div HWay Trvl Dir:
Date of Acc: 01/24/22	Legal Intervention: NO	Distance 1:
Time of Acc: 21:00 Hrs.	Private Property: NO	Direction 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Distance 2:
Officer:	Acc Loc City: MAQUOKETA - 4742	Direction 2:
Badge #: 62	Acc Dir From City:	X-Coordinate: 00693335
Report Date: 01/24/2022	Closest City:	Y-Coordinate: 04657582
Officer Notified: 21:35 Hrs.	Miles From City:	Location Literal Description: RAMP US 61 N TO SOUTH MAIN ST, N
Officer Arrived: 21:42 Hrs.	Road, Street, HWay:	
	Definable Location:	
	Milepost Number:	

Unit 001

Driver Name - Last:	Bus Use:	Transported to:
First:	Drvr Distractions: 99 - UNKNOWN	Transported by:
Middle:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
City:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
State:	Most Damaged Area: 14 - UNDERCARRIAGE	Cont. Circum., Drvr: 99 - UNKNOWN
Zip:	Undrrid/Ovrid: 8 - OTHER	
Suffix:	Rpr/Rplc Cost: \$10,000.00	Carrier Name:
Gender:	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	Carrier Address:
Age:	First Event: 99 - UNKNOWN	Carrier City:
CDL:		Carrier State:
License State:		Carrier Zip:
License Class:		Cargo Body Type: 01 - NOT APPLICABLE
License Endorsmnt:		Number of Axles:
License Restrictions:		HazMat Involvement:
Speed Limit: 35		HazMat Placard:
Seating Position:		Placard #:
	Second Event:	HazMat Released?:
Driver Condition: 99 - UNKNOWN	Third Event:	Converter Dolly:
Alcohol Test Given:	Fourth Event:	GVWR:
Drug Test Given:	Most Harmful Event: 99 - UNKNOWN	Cit Chrg Code 1:
Total Occupants: 1	Abg Switch Stat:	Citation Charge 1:
Vehicle Year: 2016	Abg Deploy:	Cit Chrg Code 2:
Vehicle Make: NISSAN - NISS	Trapped:	Citation Charge 2:
Vehicle Model: RGE	Ejection:	Citation Charge 3:
Vehicle Style: SW	Ejection Path:	Citation Charge 4:
Vehicle Color: GREEN - GRN	Occpnt Protect:	
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Source of Trans:	
Vehicle Defect: 99 - UNKNOWN	Died at Scene:	
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #:		
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Property Damage 001

Object Damaged: LIGHT POLE	Company Owner Name: IOWA DOT
Estimate of Damage: \$1,000.00	City:
Owner's Name - Last: IOWA	State:
First: STATE	Zip Code:
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 02 - SHOULDER	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 4 - DARK, ROADWAY LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 21 - OFF-RAMP, DIVERGE AREA
Surface Conditions: 03 - ICE/FROST	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 99 - UNKNOWN
Type:	
Workers Present:	