

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **2022-3597**
 Date of Acc: **03/12/22**
 Time of Acc: **11:28** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **ASST CHIEF JASON THOMSON**
 Badge #: **61**
 Report Date: **03/12/2022**
 Officer Notified: **11:28** Hrs.
 Officer Arrived: **11:31** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00691887**
 Y-Coordinate: **04659936**
 Location Literal: **WESTGATE DR**
 Description:

Unit 001

Driver Name - Last: **MANIKOWSKI**
 First: **VICTORIA**
 Middle: **ANN**
 City: **MAQUOKETA**
 State: **IA**
 Zip: **52060-0000**
 Suffix:
 Gender: **Female**
 Age: **70**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions:
 Speed Limit: **25**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2016**
 Vehicle Make: **TOYOTA - TOYT**
 Vehicle Model: **COA**
 Vehicle Style: **4D**
 Vehicle Color: **SILVER - SIL**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **01 - NORTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **04 - REAR PASSENGER SIDE**
 Most Damaged Area: **04 - REAR PASSENGER SIDE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$1,000.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event: **33 - VEHICLE IN TRAFFIC**
 Third Event: **33 - VEHICLE IN TRAFFIC**
 Fourth Event: **33 - VEHICLE IN TRAFFIC**
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: MUHLHAUSEN	Bus Use:	Transported to:
First: CARL		
Middle: ALAN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 10 - FRONT DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 10 - FRONT DRIVER SIDE	Cont. Circum., Drvr: 44 - FTYROW: FROM DRIVEWAY
Age: 60	Undrrid/Ovrid: 1 - NONE	
CDL: YES	Rpr/Rplc Cost: \$100.00	
License State: IA	Ext of Damage: 1 - NONE	
License Class: B	First Event: 34 - RE-ENTERING ROADWAY	
License Endorsmnt: LNPS		Carrier Name:
License Restrictions: KM		Carrier Address:
Speed Limit: 0		Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 33 - VEHICLE IN TRAFFIC	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier Zip:
Alcohol Test Given: NO	Third Event: 33 - VEHICLE IN TRAFFIC	Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE		
Total Occupants: 1	Fourth Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
Vehicle Year: 2016		HazMat Involvement:
Vehicle Make: JEEP - JEEP		HazMat Placard:
Vehicle Model: GCH	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Style: UT		HazMat Released?:
Vehicle Color: BLUE - BLU	Abg Switch Stat: 03 - NOT DEPLOYED	Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Defect: 01 - NONE		Cit Chrg Code 1:
	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
Vehicle Action: 98 - OTHER (EXPLAIN IN NARRATIVE)	Ejection: 2 - NOT EJECTED	
Tow: 1 - DRIVEN AWAY	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
		Citation Charge 2:
Tow #:	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	
Initial Trvl Dir: 04 - WEST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 04 - DRIVEWAY ACCESS (WITHIN)
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit one was north bound on Westgate Drive when unit two pulled out of a private drive and didn't see unit one and the front tire on unit two struck unit one causing minor damage to unit one. No visible damage to unit two. No injuries were reported.

No Diagram units were moved from road way prior to officers arrival.