

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Law Enforcement  
 Case Number: **22-3980**  
 Date of Acc: **03/18/22**  
 Time of Acc: **17:28** Hrs.  
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**  
 Officer: **OFFICER JAYSON HEIAR**  
 Badge #: **58**  
 Report Date: **03/18/2022**  
 Officer Notified: **17:28** Hrs.  
 Officer Arrived: **17:32** Hrs.

Scene Investigated: **YES**  
 Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **JACKSON - 49**  
 Acc Loc City: **MAQUOKETA - 4742**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00693179**  
 Y-Coordinate: **04658662**  
 Location Literal: **900-BLK S MAIN ST**  
 Description:

**Unit 001**

Driver Name - Last: **ORSBORNE**  
 First: **NIKITA**  
 Middle: **ROSE**  
 City: **MAQUOKETA**  
 State: **IA**  
 Zip: **52060-0000**  
 Suffix:  
 Gender: **Female**  
 Age: **17**  
 CDL: **NO**  
 License State: **IA**  
 License Class: **C**  
 License Endorsmnt:  
 License Restrictions: **Y**  
 Speed Limit: **25**  
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**  
 Driver Condition: **01 - APPARENTLY NORMAL**  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **3**  
 Vehicle Year: **2011**  
 Vehicle Make: **GENERAL MOTORS - GMC**  
 Vehicle Model: **TRN**  
 Vehicle Style: **SW**  
 Vehicle Color: **WHITE - WHI**  
 Vehicle Config: **03 - SPORT UTILITY VEHICLE**  
 Vehicle Defect: **01 - NONE**  
 Vehicle Action: **11 - STOPPED IN TRAFFIC**  
 Tow: **1 - DRIVEN AWAY**  
 Tow #:  
 Initial Trvl Dir: **03 - SOUTH**  
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:  
 Dvr Distractions: **02 - NOT DISTRACTED**  
 Traffic Controls: **01 - NO CONTROLS PRESENT**  
 Point of Init Impact: **05 - REAR PASSENGER SIDE CORNER**  
 Most Damaged Area: **05 - REAR PASSENGER SIDE CORNER**  
 Undrrid/Ovrid: **1 - NONE**  
 Rpr/Rplc Cost: **\$2,000.00**  
 Ext of Damage: **3 - FUNCTIONAL DAMAGE**  
 First Event: **33 - VEHICLE IN TRAFFIC**  
 Second Event: **38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O**  
 Third Event:  
 Fourth Event:  
 Most Harmful Event: **38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O**  
 Abg Switch Stat:  
 Abg Deploy: **03 - NOT DEPLOYED**  
 Trapped: **1 - NOT TRAPPED/APPLICABLE**  
 Ejection: **2 - NOT EJECTED**  
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**  
 Occpnt Protect: **99 - UNKNOWN**  
**5 - UNINJURED**  
 Source of Trans: **01 - NOT TRANSPORTED**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func: **01 - NO SPECIAL FUNCTION**  
 Emergency Status: **01 - NOT APPLICABLE**  
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1:  
 Citation Charge 1:  
 Cit Chrg Code 2:  
 Citation Charge 2:  
 Citation Charge 3:  
 Citation Charge 4:

**Unit 002**

Driver Name - Last: <b>BROMLEY</b>	Bus Use:	Transported to:
First: <b>PAISLEY</b>		
Middle: <b>MARIE</b>	Drvr Distractions: <b>15 - INATTENTIVE/LOST IN THOUGHT</b>	Transported by:
City: <b>MAQUOKETA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
State: <b>IA</b>	Point of Init Impact: <b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Zip: <b>52060-0000</b>	Most Damaged Area: <b>11 - FRONT DRIVER SIDE CORNER</b>	Cont. Circum., Drvr: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>
Suffix:	Undrrid/Ovrid: <b>1 - NONE</b>	
Gender: <b>Female</b>	Rpr/Rplc Cost: <b>\$2,000.00</b>	Carrier Name:
Age: <b>19</b>	Ext of Damage: <b>3 - FUNCTIONAL DAMAGE</b>	Carrier Address:
CDL: <b>NO</b>	First Event: <b>33 - VEHICLE IN TRAFFIC</b>	Carrier City:
License State: <b>IA</b>		Carrier State:
License Class: <b>C</b>	Second Event: <b>38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O</b>	Carrier Zip:
License Endorsmnt:	Third Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
License Restrictions:	Fourth Event:	Number of Axles:
Speed Limit: <b>25</b>	Most Harmful Event: <b>38 - STRUCK/STRUCK BY OBJECT/CARGO/PERSON FROM O</b>	HazMat Involvement:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Abg Switch Stat: <b>03 - NOT DEPLOYED</b>	HazMat Placard:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	Placard #:
Alcohol Test Given: <b>NO</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:
Drug Test Given: <b>1 - NONE</b>	Ejection: <b>2 - NOT EJECTED</b>	Converter Dolly:
Total Occupants: <b>1</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:
Vehicle Year: <b>2007</b>	Occpnt Protect: <b>99 - UNKNOWN</b>	Cit Chrg Code 1:
Vehicle Make: <b>HYUNDAI - HYUN</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Citation Charge 1:
Vehicle Model: <b>SFE</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:
Vehicle Style: <b>SW</b>		Citation Charge 2:
Vehicle Color: <b>GREEN - GRN</b>		Citation Charge 3:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>		Citation Charge 4:
Vehicle Defect: <b>01 - NONE</b>		
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>		
Tow: <b>1 - DRIVEN AWAY</b>		
Tow #:		
Initial Trvl Dir: <b>03 - SOUTH</b>		
Vision Obscured: <b>01 - NOT OBSCURED</b>		

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>03 - REAR END (FRONT TO REAR)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>05 - RAIN</b>	Type of Road Junc/Feat: <b>05 - DRIVEWAY ACCESS (RELATED, NOT IN)</b>
Surface Conditions: <b>02 - WET</b>	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>33 - VEHICLE IN TRAFFIC</b>
Type:	
Workers Present:	

**Narrative**

Unit 001 was stopped in traffic waiting for traffic to clear to make a left turn into the Horseshoe Pond Recreational Park. Unit 002 did not see that Unit 001 was stopped and struck the right rear corner of Unit 001 with the front left corner of Unit 002. Both vehicles were driveable with functional damage to both.

Diagram

