

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Law Enforcement  
 Case Number: **2022-8916**  
 Date of Acc: **06/01/22**  
 Time of Acc: **13:00** Hrs.  
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**  
 Officer: **OFFICER SCOTT HANSEN**  
 Badge #: **54**  
 Report Date: **06/01/2022**  
 Officer Notified: **13:06** Hrs.  
 Officer Arrived: **13:06** Hrs.

Scene Investigated: **YES**  
 Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **JACKSON - 49**  
 Acc Loc City: **MAQUOKETA - 4742**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00693128**  
 Y-Coordinate: **04660268**  
 Location Literal: **NORTH MAIN ST**  
 Description:

**Unit 001**

Driver Name - Last: **SKLADZIEN**  
 First: **BRANDON**  
 Middle: **CORNELIUS**  
 City: **MAQUOKETA**  
 State: **IA**  
 Zip: **52060-0000**  
 Suffix:  
 Gender: **Male**  
 Age: **15**  
 CDL: **NO**  
 License State: **IA**  
 License Class: **C**  
 License Endorsmnt:  
 License Restrictions: **2**  
 Speed Limit: **20**  
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**  
 Driver Condition: **01 - APPARENTLY NORMAL**  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **2**  
 Vehicle Year: **2003**  
 Vehicle Make: **PONTIAC - PONT**  
 Vehicle Model: **BON**  
 Vehicle Style: **4D**  
 Vehicle Color: **RED - RED**  
 Vehicle Config: **01 - PASSENGER CAR**  
 Vehicle Defect: **01 - NONE**  
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**  
 Tow: **1 - DRIVEN AWAY**  
 Tow #:  
 Initial Trvl Dir: **01 - NORTH**  
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:  
 Dvr Distractions: **10 - PASSENGER**  
 Traffic Controls: **04 - STOP SIGNS**  
 Point of Init Impact: **12 - FRONT MIDDLE**  
 Most Damaged Area: **12 - FRONT MIDDLE**  
 Undrrid/Ovrid: **1 - NONE**  
 Rpr/Rplc Cost: **\$100.00**  
 Ext of Damage: **2 - MINOR DAMAGE**  
 First Event: **33 - VEHICLE IN TRAFFIC**  
 Second Event:  
 Third Event:  
 Fourth Event:  
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**  
 Abg Switch Stat:  
 Abg Deploy: **03 - NOT DEPLOYED**  
 Trapped: **1 - NOT TRAPPED/APPLICABLE**  
 Ejection: **2 - NOT EJECTED**  
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**  
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**  
**5 - UNINJURED**  
 Source of Trans: **01 - NOT TRANSPORTED**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func: **01 - NO SPECIAL FUNCTION**  
 Emergency Status: **01 - NOT APPLICABLE**  
 Cont. Circum., Dvr: **97 - FTYROW: OTHER (EXPLAIN IN NARRATIVE), 58 - OPERATOR INEXPERIENCE**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1:  
 Citation Charge 1:  
 Cit Chrg Code 2:  
 Citation Charge 2:  
 Citation Charge 3:  
 Citation Charge 4:

**Unit 002**

Driver Name - Last: <b>ELLENZ</b>	Bus Use:	Transported to:
First: <b>FRANK</b>		
Middle: <b>MICHAEL</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>KIELER</b>		
State: <b>WI</b>	Traffic Controls: <b>04 - STOP SIGNS</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>53812-9110</b>		
Suffix:	Point of Init Impact: <b>06 - REAR MIDDLE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Male</b>		
Age: <b>67</b>	Most Damaged Area: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
CDL: <b>NO</b>	Undridd/Ovrid: <b>1 - NONE</b>	
License State: <b>WI</b>	Rpr/Rplc Cost: <b>\$0.00</b>	
License Class: <b>BCD</b>	Ext of Damage: <b>1 - NONE</b>	
License Endorsmnt:	First Event: <b>33 - VEHICLE IN TRAFFIC</b>	
License Restrictions: <b>B</b>		Carrier Name:
Speed Limit: <b>20</b>	Second Event:	Carrier Address:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>		Carrier City:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Third Event:	Carrier State:
Alcohol Test Given: <b>YES</b>		Carrier Zip:
Drug Test Given: <b>1 - NONE</b>	Fourth Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Total Occupants: <b>1</b>		
Vehicle Year: <b>2020</b>	Most Harmful Event: <b>33 - VEHICLE IN TRAFFIC</b>	Number of Axles:
Vehicle Make: <b>FORD - FORD</b>	Abg Switch Stat:	HazMat Involvement:
Vehicle Model: <b>RNG</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	HazMat Placard:
Vehicle Style: <b>PK</b>		Placard #:
Vehicle Color: <b>RED - RED</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:
Vehicle Config: <b>02 - FOUR-TIRE TRUCK (PICK-UP)</b>	Ejection: <b>2 - NOT EJECTED</b>	Converter Dolly:
Vehicle Defect: <b>01 - NONE</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:
	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>		Citation Charge 1:
Tow: <b>1 - DRIVEN AWAY</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 2:
	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 2:
Tow #:		Citation Charge 3:
Initial Trvl Dir: <b>01 - NORTH</b>		Citation Charge 4:
Vision Obscured: <b>01 - NOT OBSCURED</b>		

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>03 - REAR END (FRONT TO REAR)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>12 - FOUR-WAY INTERSECTION</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>33 - VEHICLE IN TRAFFIC</b>
Workers Present:	

**Narrative**

On 6/1/22 at approximately 1:06 PM vehicle 2 was stopping at the stop sign on N. Main and Quarry St. Vehicle 1 stated that he was distracted talking to his passenger and didn't see vehicle 1 stop in front of him. Vehicle 2 hit the back of vehicle 1. There was no damage to vehicle 2 and only very minor damage to vehicle 1.

Diagram

