

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22-9152**
 Date of Acc: **06/04/22**
 Time of Acc: **16:29** Hrs.
 Name of Agency: **MAQUOKETA POLICE DEPARTMENT**
 Officer: **OFFICER CORY PIRTLE**
 Badge #: **60**
 Report Date: **06/04/2022**
 Officer Notified: **16:30** Hrs.
 Officer Arrived: **16:32** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **YES**
 County: **JACKSON - 49**
 Acc Loc City: **MAQUOKETA - 4742**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00691887**
 Y-Coordinate: **04659914**
 Location Literal: **104 WESTGATE DR**
 Description:

Unit 001

Driver Name - Last: **RODGERS**
 First: **JOHN**
 Middle: **RYAN**
 City: **FORT MADISON**
 State: **IA**
 Zip: **52627-0000**
 Suffix:
 Gender: **Male**
 Age: **34**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt: **L**
 License Restrictions:
 Speed Limit: **5**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **2**
 Vehicle Year: **2007**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **TBZ**
 Vehicle Style: **UT**
 Vehicle Color: **BLACK - BLK**
 Vehicle Config: **03 - SPORT UTILITY VEHICLE**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **99 - UNKNOWN**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **11 - FRONT DRIVER SIDE CORNER**
 Most Damaged Area: **11 - FRONT DRIVER SIDE CORNER**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$500.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**
 Source of Trans:
 Died at Scene:

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: ZEALLEY	Bus Use:	Transported to:
First: ZACHARY		
Middle: ALAN	Drvr Distractions: 97 - OTHER DISTRACTION INSIDE VEHICLE (EXPLAIN IN NARRATIVE)	Transported by:
City: LA MOTTE	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 06 - REAR MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Zip: 52054-0000	Most Damaged Area: 06 - REAR MIDDLE	Cont. Circum., Drvr: 19 - STARTING OR BACKING IMPROPERLY
Suffix:	Undrriid/Ovrid: 1 - NONE	
Gender: Male	Rpr/Rplc Cost: \$100.00	
Age: 35	Ext of Damage: 1 - NONE	
CDL: NO	First Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Name:
License State: IA	Second Event:	Carrier Address:
License Class: C	Third Event:	Carrier City:
License Endorsmnt:	Fourth Event:	Carrier State:
License Restrictions:	Most Harmful Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Zip:
Speed Limit: 5	Abg Switch Stat:	Cargo Body Type: 01 - NOT APPLICABLE
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 03 - NOT DEPLOYED	Number of Axles:
Driver Condition: 06 - UNDER THE INFLUENCE O	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Involvement:
Alcohol Test Given: YES	Ejection: 2 - NOT EJECTED	HazMat Placard:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Placard #:
Total Occupants: 1	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	HazMat Released?:
Vehicle Year: 2014	Source of Trans: 01 - NOT TRANSPORTED	Converter Dolly:
Vehicle Make: FORD - FORD	Died at Scene: 01 - NOT APPLICABLE	GVWR:
Vehicle Model: F15		Cit Chrg Code 1: 321J.2(2)(A)
Vehicle Style: PK		Citation Charge 1: OPERATING WHILE UNDER THE INFLUENCE 1ST OFFENSE
Vehicle Color: ORANGE - ONG		Cit Chrg Code 2:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Citation Charge 2:
Vehicle Defect: 01 - NONE		Citation Charge 3:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 4:
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir: 99 - UNKNOWN		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 98 - OTHER (EXPLAIN IN NARRATIVE)	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 98 - OTHER (EXPLAIN IN NARRATIVE)
Type:	
Workers Present:	

Narrative

Unit 1 was parked at a gas pump. Unit 2 backed up and did not see unit 1. Unit 2 struck Unit 1 in the front bumper with the trailer hitch. There was no damage done to Unit 2. Unit 1 had small fender damage.

Diagram

