

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 2021-8956	Report to All Drivers:	At Intersection with:
Date of Acc: 06/15/21	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 17:17 Hrs.	Private Property: NO	Distance 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Direction 1:
	Acc Loc City: MAQUOKETA - 4742	Distance 2:
Officer: OFFICER SCOTT HANSEN	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00693152
Badge #: 54	Miles From City:	Y-Coordinate: 04659932
Report Date: 06/15/2021	Road, Street, HWay:	Location Literal: E PLEASANT ST
Officer Notified: 17:18 Hrs.	Definable Location:	Description:
Officer Arrived: 17:22 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: SNYDER	Bus Use:	Transported to: JCRHC
First: SHERI		
Middle: THERESE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: AMBULANCE
City: MAQUOKETA		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female		
Age: 53	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 18 - SWERVED TO AVOID: VEHICLE, OBJECT, NON-MOTORIST, OR ANIMAL IN ROADWAY
CDL: NO		
License State: IA	Undridd/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$2,000.00	
License Endorsmnt:	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Restrictions:	First Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier Name:
Speed Limit: 20		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 01 - RAN OFF ROAD, RIGHT	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier State:
Alcohol Test Given: NO	Third Event: 97 - OTHER FIXED OBJECT (EXPLAIN IN NARRATIVE)	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 3	Fourth Event:	
Vehicle Year: 1999		Number of Axles:
Vehicle Make: BUICK - BUIC	Most Harmful Event: 97 - OTHER FIXED OBJECT (EXPLAIN IN NARRATIVE)	HazMat Involvement:
Vehicle Model: CENTURY		HazMat Placard:
Vehicle Style: 4D	Abg Switch Stat:	Placard #:
Vehicle Color: WHITE - WHI	Abg Deploy: 04 - DEPLOYED FRONT OF PERSON	HazMat Released?:
Vehicle Config: 01 - PASSENGER CAR		Converter Dolly:
Vehicle Defect: 02 - BRAKE SYSTEM	Trapped: 1 - NOT TRAPPED/APPLICABLE	GVWR:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection: 2 - NOT EJECTED	Cit Chrg Code 1:
Tow: 3 - DISABLED - OFFICER ARRANGED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Citation Charge 1:
Tow #: 21-112	Occpnt Protect: 99 - UNKNOWN	Cit Chrg Code 2:
Initial Trvl Dir: 01 - NORTH		Citation Charge 2:
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 03 - EMS GROUND	Citation Charge 3:
	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Property Damage 001

Object Damaged: PLANTER BOX	Company Owner Name: CITY OF MAQUOKETA
Estimate of Damage: \$1,000.00	City: MAQUOKETA
Owner's Name - Last:	State: IA
First:	Zip Code: 52060
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 97 - OTHER FIXED OBJECT (EXPLAIN IN NARRATIVE)
Type:	
Workers Present:	

Injured Person 001

Name - Last:	HANSEN	Airbag Deployment:	04 - DEPLOYED FRONT OF PERSON
First:	TERRY	Airbag Switch Status:	
Middle:	LEONARD	Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	1 - FATAL
City:	DEWITT	Ejection:	1 - NOT APPLICABLE
State:	IA	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
Zip Code:	52742	Alcohol Test Given:	
Age:	77	Drug Test Given:	
Sex:	MALE	Source of Transport:	03 - EMS GROUND
Unit No.:	1	Died at Scene/Enroute:	04 - DIED AT HOSPITAL
Seating Position:	03 - 1ST ROW: RIGHT SIDE	Transported to:	JCRHC
Occupant Protection:	99 - UNKNOWN	Transported by:	AMBULANCE

Injured Person 002

Name - Last:	HAYTON	Airbag Deployment:	01 - NOT APPLICABLE
First:	ROBERT	Airbag Switch Status:	
Middle:	EDWARD	Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	2 - SUSPECTED SERIOUS/INCAPACITATING
City:	DEWITT	Ejection:	2 - NOT EJECTED
State:	IA	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
Zip Code:	52742	Alcohol Test Given:	
Age:	63	Drug Test Given:	
Sex:	MALE	Source of Transport:	03 - EMS GROUND
Unit No.:	1	Died at Scene/Enroute:	01 - NOT APPLICABLE
Seating Position:	06 - 2ND ROW: RIGHT SIDE	Transported to:	JCRHC
Occupant Protection:	99 - UNKNOWN	Transported by:	AMBULANCE

Narrative

On 6.15.21 at approximately 17:17 hours Vehicle 1 was traveling north on S. Main St in the 200 block when the driver stated that her brakes did not work. Vehicle 1 was not slowing down for the stop sign at S. Main and Pleasant St. Vehicle 1 attempted to use the brakes and then put the car in neutral trying to get it to slow or stop which was ineffective. There was a vehicle stopped at the stop sign on S. Main and Pleasant St so Vehicle 1 took evasive action and turned the car away from the stopped vehicle striking a limestone planter box along the sidewalk causing the vehicle to be heavily damaged and resulting in injuries to all three occupants inside of Vehicle 1. All three occupants were transported by ambulance to the JCRHC for injuries sustained in the accident. This accident is still under investigation.

Diagram

