

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 2020-10842	Report to All Drivers:	At Intersection with:
Date of Acc: 07/28/20	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 09:45 Hrs.	Private Property: YES	Distance 1:
Name of Agency: MAQUOKETA POLICE DEPARTMENT	County: JACKSON - 49	Direction 1:
	Acc Loc City: MAQUOKETA - 4742	Distance 2:
Officer:	Acc Dir From City:	Direction 2:
OFFICER JASON THOMSON	Closest City:	X-Coordinate: 00693860
Badge #: 61	Miles From City:	Y-Coordinate: 04660117
Report Date: 07/28/2020	Road, Street, HWay:	Location Literal: STATE 64/E PLATT ST
Officer Notified: 09:46 Hrs.	Definable Location:	Description:
Officer Arrived: 09:51 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: LAUGHLIN	Bus Use:	Transported to:
First: CAROLYN		
Middle: D	Drvr Distractions: 99 - UNKNOWN	Transported by:
City: MAQUOKETA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 05 - REAR PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip: 52060-0000	Most Damaged Area: 05 - REAR PASSENGER SIDE CORNER	Cont. Circum., Drvr: 99 - UNKNOWN
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender: Female	Rpr/Rplc Cost: \$800.00	Carrier Name:
Age: 65	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
CDL: NO	First Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier City:
License State: IA	Second Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier State:
License Class: C	Third Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Zip:
License Endorsmnt:	Fourth Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Number of Axles:
Speed Limit: 0	Abg Switch Stat:	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 01 - NOT APPLICABLE	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Alcohol Test Given: NO	Ejection: 1 - NOT APPLICABLE	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Total Occupants: 1	Occpnt Protect: 01 - NOT APPLICABLE	GVWR:
Vehicle Year: 2006		Cit Chrg Code 1:
Vehicle Make: DODGE - DODG	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Vehicle Model: R15	Died at Scene: 01 - NOT APPLICABLE	
Vehicle Style: PK		Cit Chrg Code 2:
Vehicle Color: RED - RED		Citation Charge 2:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		
Vehicle Defect: 99 - UNKNOWN		Citation Charge 3:
Vehicle Action: 98 - OTHER (EXPLAIN IN NARRATIVE)		
Tow: 1 - DRIVEN AWAY		Citation Charge 4:
Tow #:		
Initial Trvl Dir: 99 - UNKNOWN		
Vision Obscured: 01 - NOT OBSCURED		

Unit 002

Driver Name - Last: YAROLEM	Bus Use:	Transported to:
First: MICHAEL		
Middle: CHARLES	Drvr Distractions: 99 - UNKNOWN	Transported by:
City: MAQUOKETA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52060-0000		
Suffix:	Point of Init Impact: 04 - REAR PASSENGER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 04 - REAR PASSENGER SIDE	Cont. Circum., Drvr: 99 - UNKNOWN
Age: 61	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$500.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Name:
License Endorsmnt:	Second Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Address:
License Restrictions: F	Third Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier City:
Speed Limit: 0	Fourth Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Most Harmful Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Abg Switch Stat: 01 - NOT APPLICABLE	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Abg Deploy: 01 - NOT APPLICABLE	Number of Axles:
Drug Test Given: 1 - NONE	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Involvement:
Total Occupants: 1	Ejection: 1 - NOT APPLICABLE	HazMat Placard:
Vehicle Year: 1995	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Placard #:
Vehicle Make: CHEVROLET - CHEV	Occpnt Protect: 01 - NOT APPLICABLE	HazMat Released?:
Vehicle Model: C15	Source of Trans: 01 - NOT TRANSPORTED	Converter Dolly:
Vehicle Style: PK	Died at Scene: 01 - NOT APPLICABLE	GVWR:
Vehicle Color: MAROON, BURGUNDY (PURPL		Cit Chrg Code 1:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Citation Charge 1:
Vehicle Defect: 99 - UNKNOWN		Cit Chrg Code 2:
Vehicle Action: 99 - UNKNOWN		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #:		Citation Charge 4:
Initial Trvl Dir: 99 - UNKNOWN		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 99 - UNKNOWN	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 99 - UNKNOWN
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 98 - OTHER (EXPLAIN IN NARRATIVE)
Type:	
Workers Present:	

Narrative

Unit one was backing out of parking spot in Casey's General Store parking lot and backed into unit two that was parked at the gas pumps. Unit two was towing a small flatbed utility trailer. Unit one struck the fender well of the trailer causing minor damage to unit two trailer. Unit one had minor damage to rear bumper. No injuries were reported. This incident happened private property. No citations were issued.

No Diagram / Private
Property